

**EXAMINATION REPORT
PHOTOGRAPHS OF STRUCTURE**

ELR: BAL Br. No.: 00

Mileage: 10 M 17 ch Sheet 23 of 29



Photo No.34: 043+17 Solum Up, broken out catch-pit dumped in cess.



Photo No.35: 046+00 to 048+20 Sidewall & Haunches Up & Down, Brickwork, bulging 75mm with random vertical and longitudinal fractures, max. width 1mm, hollow, area 20sq.m.

**EXAMINATION REPORT
PHOTOGRAPHS OF STRUCTURE**

ELR: BAL Br. No.: 00

Mileage: 10 M 17 ch Sheet 24 of 29



Photo No.36: 046+10 Refuge Down, Brickwork, spalling, depth 100mm, area 2sq.m., vertical fractures, length 1.6m to both Quoins, hollow.



Photo No.37: 061+19 to 062+00 Solum Down, 2No. trial pits. Partially backfilled.

**EXAMINATION REPORT
PHOTOGRAPHS OF STRUCTURE**

ELR: BAL Br. No.: 00

Mileage: 10 M 17 ch Sheet 25 of 29



Photo No.38: 062+00 Solum Up, workman toilet waste, hazard.



Photo No.39: 062+15 to 073+05 Solum Up & Down, drainage WIP, catch-pits and/or earthenware pipes broken out, new inspection chambers fitted proud on solum, hazard.

**EXAMINATION REPORT
PHOTOGRAPHS OF STRUCTURE**

ELR: BAL Br. No.: 00

Mileage: 10 M 17 ch Sheet 26 of 29



Photo No.40: 062+15 to 073+05 Solum Up & Down, drainage WIP, catch-pits and/or earthenware pipes broken out, new inspection chambers fitted proud on solum, hazard.



Photo No.41: 062+15 to 073+05 Solum Up & Down, drainage WIP, catch-pits and/or earthenware pipes broken out, new inspection chambers fitted proud on solum, hazard.

**EXAMINATION REPORT
PHOTOGRAPHS OF STRUCTURE**

ELR: BAL Br. No.: 00

Mileage: 10 M 17 ch Sheet 27 of 29



Photo No.42: 063+10 Solum Up & Down, Open catch-pit to six-foot with water welling up from inside. New cover fitted but displaced/ill-fitting. Now not surcharging.



Photo No.43: Full length of tunnel, Solum Up & Down, drainage WIP, smashed track drainage pipes, poor underfoot conditions, hazard (typical example found at 071+11 cess down).

**EXAMINATION REPORT
PHOTOGRAPHS OF STRUCTURE**

ELR: BAL Br. No.: 00

Mileage: 10 M 17 ch Sheet 28 of 29



Photo No.44: 071+19 to 072+15 Solum Up & Down, Mud and flooding, depth 3".



Photo No.45: 072+11 to 073+05 Solum Up & Down, Debris.

**EXAMINATION REPORT
PHOTOGRAPHS OF STRUCTURE**

ELR: BAL Br. No.: 00

Mileage: 10 M 17 ch Sheet 29 of 29



Photo No.46: 073+05 Portal Up & Down, View of blocked up Abergwynfi Portal from inside tunnel.