

Intended works to trees on bank immediately behind the site at
Pant Howell Ddu, Ynysmaerdy.

Due to the positioning of the trees next to the site a tree survey has been carried out by Stephen Lucocq of ArbTS – Arboricultural Technician Services.

This has been included in the application see - Tree Survey.pdf

Based on the inspection of the trees in the survey it has been suggested that should planning permission for the development be granted some of the trees on surrounding bank would need works/management. The bank that they are growing on is made up of old loose coal and therefore one of the reasons that some of the trees are not very stable.

The trees below have been identified as of low-poor quality and are intended to be removed-

T3 – Tree has already fallen and is leaning on T662 and T663

T661 – Highlighted as poor quality

T662 – Highlighted as low quality and large oak tree has fallen and is leaning onto this tree.

T663 – Highlighted as low quality and large oak tree has fallen and is leaning onto this tree.

T664 – Highlighted as low quality and overhanging

T665 – Highlighted as low quality and overhanging.

T658 – Highlighted as having advanced decay.

The loss would not have a negative impact to the area and if removal of the above trees is granted we plan to re plant suitable native species similar to what are already found on site to off set the loss of the trees.

Location of trees please see attachment –
Tree Survey Proposed.pdf

Various other trees have been suggested for tree management such as pruning to reduce some branches, please see attachment for further more detailed information – Tree Survey.pdf