

Site Photographs



Sloped access path leading from the carpark to the main, northern entrance. Location and poor quality of materials acts to the detriment of the legibility of the building and access routes



*(Top) The main entrance to the north sits away from the principal car park exit and lacks a sense of arrival
(Bottom) Main exit point from carpark. Visitor centre does not present itself as a main welcome building*



*(Top) Canopy with secondary access to the café area, which has become a principal access.
(Bottom) The tramper store acts as a barrier to the building and views of the reservoir beyond.*