

**CWE Services Limited**

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work Method Statement

Client **BLUEFIELD LAND**

Site Ref

Site Address

Holly Street Pontardawe

Testing Date

Report Reference Number **N/A**

Document Issue Date **12th April 2024**

Method Statement Ref No **MS1278**

Document prepared by:

S. Emler

Document reviewed by:

N Lewis



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work Method Statement

Contents

1.	Contact / Site Particulars.....	3
2.	Site Specific Risk Assessment.....	4
3.	Reassurance Monitoring	4
4.	Emergency Procedures.....	7

Appendix A	UKAS Certificate and Schedule of Accreditation
Appendix B	Insurances
Appendix C	Generic Risk Assessment
Appendix D	COSHH – Acetone Risk Assessment
Appendix E	COSSH – Glycerol Triacetate Risk Assessment
Appendix F	Site Specific Risk Assessment

**CWE Services Limited**

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work Method Statement

1. Contact / Site Particulars

Client Name : Bluefied Land

Client Address : Atlantic Eco Park, Newton Road, Rumney, Cardiff, CF3 2EJ

Contact Name : Paul Markey

Telephone No :

E-Mail Address :

Mobile No :

Contractor Name : Neal Remediation Ltd

Contractor Address : Atlantic Eco Park, Newton Road, Rumney, Cardiff, CF3 2EJ

Contact Name :: Darren Evans

Telephone No : 02920 797835

E-Mail Address : N/A

Mobile No : N/A

Site Contact :: TBC

Telephone No : TBC

Site Address : Holly Street Pontardawe

Areas to be assessed: Details of areas to be confirmed by Client

Brief description of works to be undertaken by Contractor :

Details of works yet to be confirmed

Date(s) works to be undertaken : tbc

Scope of Analytical Works :

Carry out Perimeter Reassurance and Personal Sampling at each site as required by the site supervisor.

Testing and Clearance Work Method Statement

2. Site Specific Risk Assessment

A Site Specific Risk Assessment is to be completed for each job prior to works commencing. Additional control measures are put in place prior to any works commencing where completion of the risk assessment identifies that sufficient controls are not in place.

3. Reassurances

Reassurance Sampling

Reassurance sampling will be required in certain circumstances, for example when an enclosure is being dismantled or following disturbance of ACMs in order to determine whether the ambient fibre levels are less than 0.01 f/ml. Fewer sampling measurements may be required during Background and Reassurance sampling but each measurement must result from a total of at least 480 litres in volume.

Flow Meters

The pump flow rate should be set to within $\pm 10\%$ and preferably $\pm 5\%$ and the flow rate should be maintained for the duration of the sampling period and the flow rate is to be recorded at the start and end of the sampling period. The flow meter is to be checked after each hour of sampling. If the check indicates that the deviation is greater than $\pm 5\%$ the test is to be stopped and the pump removed from use.

Preparation of Filter Holders

- Any filter holders and cowls being re-used must be cleaned before use and filters should be loaded, unloaded and analysed in an area as free from fibre contamination as possible.
- Handle the filter at all times with clean flat-tipped tweezers. Grip the filter at the edge, outside the exposed area.
- Place the printed grid on the filter onto the filter holder so that it faces towards the cowl.
- Close the entrance to the cowl with a protective cap or bung when sampling is not in progress.

Taking the Sample

- Remove the protective cap from the filter holder;
- Start the pump and make a note of the time;
- Measure and record the flow rate at the beginning and end of the sampling period;
- Record the time at the end of the sampling period;
- Stop the pump;
- Replace the protective cap onto the filter holder;
- Ensure that the sampling period is measured to within $\pm 2.5\%$;
- Calculate the average flow. Periodic checking and adjustment of the flow rate can be made and this should be recorded and used in the final calculations of the average flow. If the flow variation between the start and the end of the sampling period has not been maintained within $\pm 10\%$ then the sample is to be rejected. In this instance the sampler is to be removed from use immediately and procedures for damaged equipment followed. The reason for the sampler being withdrawn is to be documented on the certificate of reoccupation. The air test is to be re-run using a different sampler.

Testing and Clearance Work

Method Statement

Filter Clearing and Mounting

- Microscope slides and cover slips are to be cleaned with lens tissues and prepared for use;
- Mark the slide with the unique sample reference number, sample number and analysis date. The format to be used is the unique air test reference number followed by /01, 02 etc for each slide;
- Place the filter centrally on a clean microscope slide, sample side upwards and preferably with grid lines parallel to the slide edges. It is important that the filter is dry as water interferes with the clearing process.
- Place the slide and filter under the Acetone vaporiser nozzle and inject a small amount of Acetone into the hot block so that the vapour emerges in a steady stream over the filter. The filter should clear instantly. (Ensure that there are no naked flames in the vicinity when using the Acetone).
- Once the Acetone has evaporated place a drop or two of Triacetin on the filter using a suitable dropper. This must be just enough to cover the filter when the coverslip is in place.
- Lower the clean coverslip at an angle onto the filter so that all of the air is expelled;
- If necessary, remove any excess Triacetin from the slide using the corner of a tissue;
- The mounted filter should then be placed onto the hot plate for up to 15 minutes or until it is clear and transparent.

Evaluation

Fibre counting must be carried out under suitable background conditions, which may involve excluding bright lights (including sunlight) and undue vibration (caused by mobile engine units for example).

The microscope must be checked, adjusted and used according to the manufacturer's instructions and in-house procedures manual – Refer Appendix A - at the beginning of each counting session (or more frequently if any adjustments have made).

- Place the mounted filter slide on the microscope stage. The sample should be examined with a low power objective to check the uniformity of the deposit and that there is no gross aggregation of fibres or dust on the mounted filter and should be rejected if this is found to be the case.
- Fibres on the filter should be counted using at least X500 magnification. Higher magnifications should not exceed 1,000 times the numerical aperture of the objective lens.
- Adjust the fine focus upwards and downwards by several micrometers at each new area to ensure all fibres are seen.
- Graticule areas for counting are chosen at random. Fields lying within 4mm of the filter edge should not be counted. Reject fields if a filter grid line obstructs all or part of the field or view; more than one eighth of the graticule field area is occupied by an agglomerate of fibre and/or particles, by discrete particles or by air bubbles; the fibres are so obscured that they cannot

Testing and Clearance Work Method Statement

be counted reliably. The number of rejected fields should be noted in the final if they exceed 10% of the number accepted.

- A countable fibre is defined as any object which is longer than 5 microns with an average width less than 3 microns and having an aspect ratio (length/width) greater than 3:1. Fibres attached to particles are assessed as if the particle does not exist and are counted if the visible part of the fibre meets the above definition.
- The following rules apply :-
 - a countable fibre with both ends within the graticule area is recorded as one fibre;
 - a countable fibre with only one end in the graticule area is recorded as half a fibre;
 - a countable fibre passing through the graticule area, and having no ends within that area, is not counted;
- A split fibre is taken to be one countable fibre if it meets the definition above, otherwise it must be ignored. A split fibre is defined as an agglomerate of fibres which at one or more points on its length appears to be solid and undivided, but at other points appears to divide into separate strands. The width is measured across the undivided part, not across the split part.
- Loose agglomerates of fibres are counted individually if they can be distinguished sufficiently to determine that they meet the definition above;
- Fibres in a bundle and tight agglomerates of fibres, where no individual fibres meeting the definition of a countable fibre can be distinguished are taken to be one countable fibre if the bundle or agglomerate as a whole meets the definition above.
- If the width of the fibre varies along its length then a representative average width is to be considered.

The number of graticule areas to be counted is determined as follows:

- For evaluations related to personal sampling in connection with compliance sampling or assessment of respirator protection, at least 100 fibres must be counted or 100 graticule areas must be inspected, whichever is reached first; at least 20 graticule areas must be inspected even if these contain more than 100 fibres.
- For evaluation to the clearance indicator, background, reassurance and leak sampling, 200 graticule areas must be inspected when the minimum sample volume of 480 litres is collected.



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work Method Statement

4. Emergency Procedures

4.1 Personal Injury

- a) Ensure that the injured person is free from further injury and safe
- b) Immediately contact the client representative
- c) Immediately inform CWE Management

4.2 Fire

In the event of fire the procedure will be :-

- a) Raise the alarm, evacuate the area and assemble at the designated assembly point
- b) Immediately contact the Client Representative
- c) Immediately inform CWE Management

**CWE Services Limited**

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work - Method Statement

Appendix A – UKAS Certificate and Schedule of Accreditation

Schedule of Accreditation

issued by

United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 Accredited to ISO/IEC 17025:2017	CWE Services Ltd	
	Issue No: 007	Issue date: 01 February 2022
	The Barn Oak Farm Weston Road Congresbury North Somerset BS49 5EB	Contact: Mr Tracy Lewis Tel: +44 (0)193 483 8025 E-Mail: enquiries@cwegroup.co.uk Website: www.cwegroup.co.uk
Testing performed by the Organisation at the locations specified below		

Locations covered by the organisation and their relevant activities

Laboratory locations:

Location details		Activity	Location code
Address The Barn Oak Farm Weston Road Congresbury North Somerset BS49 5EB	Local contact Mr Tracy Lewis Tel: +44 (0)1934 838025 E-Mail: enquiries@cwegroup.co.uk Website: www.cwegroup.co.uk	Health and Hygiene Head Office Asbestos – All Support Functions	A

Site activities performed away from the locations listed above:

Location details	Activity	Location code
Client Premises	Health and Hygiene	B
Mobile Testing Laboratories	Health and Hygiene	C

Testing and Clearance Work - Method Statement

 6024 Accredited to ISO/IEC 17025:2017	Schedule of Accreditation issued by United Kingdom Accreditation Service 2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK CWE Services Ltd Issue No: 007 Issue date: 01 February 2022 Testing performed by the Organisation at the locations specified
--	---

DETAIL OF ACCREDITATION

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
ASBESTOS FIBRES IN AIR	<u>Health and Hygiene</u>	Health and Safety Executive - Asbestos: The Analysts' Guide (HSG 248) – 2021	
	Sampling of air for fibre counting	Documented In-House Method PM002 based on HSG 248	B, C
	Fibre counting	Documented In-House Method PM002, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	A, B, C
	4 Stage Clearance Process	Documented In-House Method PM002, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	B, C
ASBESTOS IN BULK MATERIALS including materials and products suspected of containing asbestos	Sampling of bulk materials for subsequent identification of asbestos	Documented In-House Method PM001 based on HSG 248 Documented In-House Method PM009 using stereo-microscopy, polarised light optical microscopy and dispersion staining based on HSG 248	B
	Identification of: Amosite Chrysotile Crocidolite Fibrous Actinolite Fibrous Anthophyllite Fibrous Tremolite		A
END			



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work - Method Statement

Appendix B –Insurances

**CWE Services Limited**

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work - Method Statement



Certificate of professional indemnity insurance C W E Services Ltd

Certificate of professional indemnity insurance

Policy number: HUPI6 9279412

Name of policy holder: C W E Services Ltd

Period of insurance: From 30 October 2023 to 29 October 2024 both days inclusive

Insurer: Hiscox Insurance Company Limited

Retroactive date:

Level of cover: £5,000,000

Signed for and on behalf of Hiscox Insurance Company Limited

Ben Horton
Executive Director, Hiscox Underwriting Ltd
Chief Underwriting Officer, Hiscox UK

Notes:

(a) This insurance is subject to policy terms and conditions and any special terms notified to the Insured

**CWE Services Limited**

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work - Method Statement



Certificate of employers' liability insurance C W E Services Ltd

Certificate of employers' liability insurance (a)

(Where required by regulation 5 of the Employers' Liability (Compulsory Insurance) Regulations 1998 and subsequently amended by regulation 2 of the Employers' Liability (Compulsory Insurance) Regulations 2008 (the regulations), one or more copies of this certificate must be displayed at each place of business at which the policyholder employs persons covered by the policy. This requirement will be satisfied if the certificate is made available in electronic form and each relevant employee to whom it relates has reasonable access to it in that form)

Policy Number	HUPI6 9279412
Name of policyholder	C W E Services Ltd
2. Date of commencement of insurance policy	30 October 2023
3. Date of expiry of insurance policy	29 October 2024
Insurer	Hiscox Insurance Company Limited

We hereby certify that subject to paragraph 2:

1. The policy to which this certificate relates satisfies the requirements of the relevant law applicable in Great Britain, Northern Ireland, the Isle of Man, the Island of Jersey, the Island of Guernsey, the Island of Alderney (b); and
2. the minimum amount of cover provided by this policy is no less than £5 million (c).

Signed on behalf of HiscoxUnderwriting Ltd as agent for the insurers

Ben Horton

Executive Director, Hiscox Underwriting Ltd

Chief Underwriting Officer, Hiscox UK

Notes:

- (a) Where the employer is a company to which regulation 3(2) of the regulations applies, the certificate shall state in a prominent place, either that the policy covers the holding company and all its subsidiaries, or that the policy covers the holding company and all its subsidiaries except any specifically excluded by name, or that the policy covers the holding company and only the named subsidiaries.
- (b) Specify applicable law as provided for in regulation 4(6) of the Regulations.
- (c) See regulation 3(1) of the Regulations and delete whichever of paragraphs 2(a) or 2(b) does not apply. Where 2(b) is applicable, specify the amount of cover provided by the relevant policy.

This certificate above shows that you are insured

- (i) with an authorised insurer, and
- (ii) in terms required by the Act for your liability for bodily injury or disease sustained by your employees.

The certificate (or any copy) must not be displayed unless the policy has been renewed.

Registered in England Number 70234

Registered Office Hiscox 22 Bishopsgate London EC2N 4BQ United Kingdom

Telephone No: 020 7448 6000

Hiscox Underwriting Ltd of 22 Bishopsgate, London EC2N 4BQ is registered in England no. 02372789. Authorised and regulated by the Financial Conduct Authority.

**CWE Services Limited**

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work - Method Statement

**Certificate of public and products liability insurance****C W E Services Ltd**

Certificate of public and products liability insurance

Insured name	C W E Services Ltd
Address	The Barn, Oak Farm Weston Road, Congresbury Bristol
Postcode	BS49 5EB
Policy number	HUPI6 9279412
Insurer	Hiscox Insurance Company Limited
Period of insurance	From 30 October 2023 to 29 October 2024 both days inclusive
Limit of Indemnity	£5,000,000

Signed for and on behalf of Hiscox Underwriting Ltd as agent for the insurers

Ben Horton

Executive Director, Hiscox Underwriting Ltd

Chief Underwriting Officer, Hiscox UK

Note: this certificate is for information purposes only and does not contain the full terms, conditions and exclusions of the insurance cover and does not constitute a contract of insurance.



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work – Method Statement

Appendix C – Generic Risk Assessment

Hazard	Risk Group			Worst Outcome				Likelihood				Risk Rating	Controls	Risk Result
	S	P	C	4	3	2	1	4	3	2	1			
Working at Heights														
Scaffolding	✓			✓						✓		Medium	Access onto scaffolding is only to be made onto scaffolding that has been erected by a company qualified to do so and must reflect the necessary safety certificates.	Low
Mobile Towers	✓			✓						✓		Medium	Access to mobile towers is only to be made if erected by a competent person to the manufacturers exact specifications. Equipment is to display these. Surfaces are to be stable and of sufficient strength to safely support the structure. Wheeled structures must be prevented from moving inadvertently. Structure must be stable and of sufficient size to allow the safe passage of persons and provide a safe working area. There are to be no gaps through which a person or materials could fall.	Low
Ladders	✓				✓			✓				High	Use of ladders to be carried out in accordance with document GD024 – Ladders Procedures and Risk Assessment. The surface on which the ladder is to rest must be stable, firm and of sufficient strength to support the ladder so that its rungs or steps remain horizontal. Suspended ladders are to be attached in a secure manner to ensure their stability. Ladders used for access must be long enough to protrude sufficiently above the place of landing to which it provides access. Interlocking or extension ladders are not to be used if its sections can move relative to each other while in use. Sufficient landing areas or rest platforms must be provided at suitable intervals where a ladder or run of ladders rises a vertical distance of 9 metres or more above its base.	Low
Fragile Surfaces	✓			✓					✓			High	Suitable and sufficient platforms, coverings or similar means of protection must be provided. Any persons at risk of injury are to be made aware of the fragile surface.	Low
Manual Handling	✓				✓				✓			Medium	Where a hazardous manual handling operation cannot be avoided a thorough assessment is to be undertaken. Only personnel adequately trained in manual handling are authorised to carry out the operation. Routes where manual handling is to take place are to be free from any trip hazards. Safe systems of work are to be adhered to. PPE is to be used where applicable to limit risks.	Low

Risk Group	Worst Outcome	Likelihood	Risk Rating
S – CWE Employees P – Public C – Contractors	4 – Fatal 3 – Major 2 – Over three day injury 1 – Slight / None	4 – Definite 3 – Probable 2 – Possible 1 – Remote	1 – 5 Low Risk 6 – 9 Medium Risk 10 – 16 High Risk
Risk Rating = Worst Outcome x Likelihood = Risk Rating			



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work – Method Statement

Hazard	Risk Group			Worst Outcome				Likelihood				Risk Rating	Controls	Risk Result
	S	P	C	4	3	2	1	4	3	2	1			
Lone Working	✓				✓			✓				High	Only medically fit and experienced personnel to carry out lone working. Ensure security arrangements are adequate. Ensure emergency procedures in place in the event of becoming ill or having an accident. Ensure correct access equipment is available and safe to use. Ensure lighting is adequate. Ensure mobile telephone is fully charged, has an adequate signal and is within reach at all times. Confirm arrival on site with dedicated person at CWE office, telephone each hour and again on departure. Advise dedicated person at CWE office of exact location on site. Establish escape routes. Lone working is not to take place if there is any risk to health and safety.	Low
Plant and Equipment	✓				✓				✓			Medium	Ensure all electrical equipment has been PAT tested and is in good condition. All electrical equipment used on site must be 110v. Ensure suitable training in the use of equipment has been carried out. Ensure eye protection, hearing protection, gloves, RPE, hard hats, safety boots etc are worn as applicable.	Low
Noise	✓	✓	✓			✓				✓		Low	Ensure adequate hearing protection is worn. Ensure adequate breaks are frequently taken away from the area.	Low
Falls, Slips and Trips	✓	✓	✓		✓					✓		Medium	Ensure that the area is free of any obstacle that could cause a slip, trip or fall. Ensure footwear is in good conditions and laces tied.	Low
Sharps	✓			✓						✓		Medium	Not to be touched. Site to be immediately vacated if the presence of sharps located. Quality Assurance Manager to be immediately notified.	Low
Inhalation of asbestos fibres during Surveying	✓	✓	✓	✓					✓			High	Asbestos surveys to be carried out in accordance with asbestos legislation and in-house procedures. Ensure suitably qualified to carry out the works. Ensure correct RPE and PPE is worn. If relevant, licensed asbestos removal contractor to be employed to erect enclosures.	Low

Risk Group	Worst Outcome	Likelihood	Risk Rating
S – CWE Employees P – Public C – Contractors	4 – Fatal 3 – Major 2 – Over three day injury 1 – Slight / None	4 – Definite 3 – Probable 2 – Possible 1 – Remote	1 – 5 Low Risk 6 – 9 Medium Risk 10 – 16 High Risk
Risk Rating = Worst Outcome x Likelihood = Risk Rating			



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work – Method Statement

Hazard	Risk Group			Worst Outcome				Likelihood				Risk Rating	Controls	Risk Result
	S	P	C	4	3	2	1	4	3	2	1			
Inhalation of asbestos fibres during air monitoring / four stage clearances	✓		✓	✓				✓				High	Ensure procedures are carried out in accordance with in-house procedures and asbestos legislation. Ensure suitably qualified to carry out the works. Ensure correct RPE and PPE is worn.	Low
Confined Space	✓			✓					✓			High	Specific risk assessment to be completed. Supervisor to be appointed to ensure necessary precautions are taken. Confined space working to have at least two personnel in attendance. Ensure suitable training has been carried out. Ensure that mechanical and electrical equipment (if applicable) is isolated. Ensure that physical isolation of pipework is made if gas, fumes or vapour could enter the confined space. Ensure that the confined space is clean. Ensure that the entrance is large enough to provide easy entry and exit, especially in the case of an emergency. Ensure that there is adequate ventilation within the confined space. If this is not the case then ensure that adequate breathing apparatus is issued and that suitable training in the use thereof has been received. Ensure that the air within the confined space is fit to breathe. Testing is to be carried out by a competent person using a suitable detector which is correctly calibrated. Continuous monitoring of the air may be required. Ensure that adequate tools, rescue harness (if applicable) and lighting are supplied. Ensure that emergency procedures are in place. Ensure that adequate communications systems are in place. Ascertain whether a permit to work is required.	Low

Risk Group	Worst Outcome	Likelihood	Risk Rating
S – CWE Employees	4 – Fatal	4 – Definite	1 – 5 Low Risk
P – Public	3 – Major	3 – Probable	6 – 9 Medium Risk
C – Contractors	2 – Over three day injury	2 – Possible	10 – 16 High Risk
	1 – Slight / None	1 – Remote	
Risk Rating = Worst Outcome x Likelihood = Risk Rating			



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work – Method Statement

Appendix D - COSHH - Acetone Risk Assessment

Description	Colourless liquid with a characteristic ethereal odour. m.p. -96 to -93°, b.p. 55-56°C. Mixable with water. CAS : 67-64-1
CWE Use	Preparation of slides for airborne fibre concentration analysis
Health Hazards	 IRRITANT Irritating to the Eyes. Exposure to high vapour concentrations or swallowing may produce central nervous system depression with headache, nausea, giddiness, unconsciousness and death. If swallowed aspiration into the lungs may cause fatal lung damage (pulmonary oedema). Eye contact with liquid causes pain and irritation. Vapour irritates the eyes and respiratory tract. Liquid degreases the skin and may cause cracking.
Safety Hazards	Incompatible with strong oxidising agents, strong acids, bromoform, chloroform and alkalies. Ignites on contact with activated carbon, chromium trioxide and potassium-tert butoxide. Explosion hazard. Forms flammable/explosive vapour/air mixtures.
Fire	 HIGHLY FLAMMABLE Flash point -19°C; Explosive limits 2.6-12.8%. In the event of fire use carbon dioxide, water spray or alcohol-resistant foam extinguishers.
Duration and Extent of Use by CWE	Acetone is used in small amounts at infrequent intervals by CWE personnel
Control Measures to be Implemented	Ensure slides are prepared in accordance with CWE in-house procedures and HSG248. Ensure that there is adequate ventilation within the area and do not inhale the Acetone. Ensure Acetone is not used near any open flame and that all electrical equipment in the vicinity is in a good condition. Ensure Acetone is stored in glass containers which are suitably labelled. Glass containers containing Acetone are to be kept safe in the equipment toolbox. Acetone held at the offices are stored in a flammable materials cabinet which is kept locked at all times. Ensure that the Acetone is kept at a moderate temperature.
First Aid	Inhalation : Remove from source of exposure. If breathing stops or shows signs of failing apply artificial respiration. Obtain medical help. Skin Contact : Remove contaminated clothing and flush the affected area with water for at least 15 minutes. Obtain medical help. Eyes : Flood with eyewash or water for at least 15 minutes. Obtain medical help. Ingestion : Wash out mouth with water. Obtain medical help.
Spillage	Small spillage amounts can be left to evaporate. Larger amounts can be diluted with large quantities of water.



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work – Method Statement

Appendix E - COSHH – Glycerol Triacetate Risk Assessment

Description	Viscous colourless liquid
CWE Use	Preparation of slides for airborne fibre concentration analysis
Health Hazards	 May cause irritation to the eyes. May cause irritation to the skin. Avoid contact to broken skin. May cause irritation to the respiratory system. Exposure should be kept to a minimum.
Safety Hazards	This product has a relatively low toxicity rating and no handling problems are likely to be encountered providing normal safe hygiene practices are applied
Fire	In the event of fire use waterspray, carbon dioxide, dry chemical powder or appropriate foam extinguishers. If involved in a fire the chemical decomposes to emit toxic fumes of carbon dioxide and carbon monoxide.
Duration and Extent of Use by CWE	Glycerol Triacetate is used in small amounts at infrequent intervals by CWE personnel
Control Measures to be Implemented	Ensure slides are prepared in accordance with CWE in-house procedures and HSG248. Ensure that there is adequate ventilation within the area and do not inhale the chemical fumes. Ensure chemical is stored in suitable containers which are clearly labelled. Containers containing the chemical are to be kept safe in the equipment toolbox. Glycerol Triacetate held at the offices is stored in a flammable materials cabinet which is kept locked at all times. Ensure that the chemical is kept at a moderate temperature. Use of gloves and eye protection is recommended but not obligatory.
First Aid	Inhalation : Remove from area. Obtain medical advice if necessary. Skin Contact : Flush area with large quantities of running water. Obtain medical advise in the event of irritation occurring. Eyes : Was out immediately with fresh running water or saline solution for at least 15 minutes. If pain persists or recurs seek medical attention. Ingestion : If the chemical has been confined to the mouth use large quantities of water as a mouth wash. Ensure the mouth wash is not swallowed, If the chemical has been swallowed drink approximately 250ml of water to dilute it in the stomach. In severe cases seek medical attention.
Spillage	Small spillage amounts can be wiped up with a cloth which is to be placed into a suitable labelled container for disposal.



CWE Services Limited

The Barn
Oak Farm
Weston Road
Congresbury
North Somerset
BS49 5EB

Tel: 0871 2000 900
Fax: 0871 2000 902
enquiries@cwegroup.co.uk

Reg No : 4070169

Document Ref : TD008 V1



Testing and Clearance Work - Method Statement

Appendix F – Site Specific Risk Assessment

**Site Specific Risk Assessment is automatically generated by
TEAMS prior to any works commencing software**