

Hi Russell

As requested.

The coffee shop accept the flood the flood risk C1 at the premises and the consequences associated. The mitigation measures regarding the plug sockets are as follows.

The actual ground level of coffee kitchen area is 300mm raised above floor level as it's a refurbished lorry refrigeration unit. With all plug sockets a further 800mm above respected floor level.

I hope this is satisfactory to your requirements.

Regards

Richard Taylor