

Trial Pit Photographs



Soil Mechanics



Trial Pit C1

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E1
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Soil Mechanics



Trial Pit C1

Notes:

Project Coed Darcy Urban Village, Junction 43 Improvements
Project No. H1065-11
Carried out for Dawnus Construction Ltd.

Figure

E2

Trial Pit Photographs



Trial Pit C2

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E3
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Trial Pit C2

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E4
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Trial Pit C3

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E5
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Soil Mechanics



Trial Pit C3

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E6
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Trial Pit C4

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E7
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Soil Mechanics



Trial Pit C4

Notes:

Project Coed Darcy Urban Village, Junction 43 Improvements
Project No. H1065-11
Carried out for Dawnus Construction Ltd.

Figure

E8

Trial Pit Photographs



Trial Pit C5

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E9
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Soil Mechanics



Trial Pit C5

Notes:

Project Coed Darcy Urban Village, Junction 43 Improvements
Project No. H1065-11
Carried out for Dawnus Construction Ltd.

Figure

E10

Trial Pit Photographs



Soil Mechanics



Trial Pit C6

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E11
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Soil Mechanics



Trial Pit C6

Notes:

Project Coed Darcy Urban Village, Junction 43 Improvements
Project No. H1065-11
Carried out for Dawnus Construction Ltd.

Figure

E12


Trial Pit Photographs



Trial Pit C7

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E13
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Trial Pit C7

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E14
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Soil Mechanics



Trial Pit C8

Notes:	Project	Coed Darcy Urban Village, Junction 43 Improvements	Figure E15
	Project No.	H1065-11	
	Carried out for	Dawnus Construction Ltd.	

Trial Pit Photographs



Soil Mechanics



Trial Pit C8

Notes:

Project Coed Darcy Urban Village, Junction 43 Improvements
Project No. H1065-11
Carried out for Dawnus Construction Ltd.

Figure

E16