


CDM notes are provided to assist the contractor in managing residual hazards identified during the design stage. Any such notes do not relieve the contractor of their duties under all relevant CDM Regulations.



**rio** [studio@rioarchitects.com](mailto:studio@rioarchitects.com)  
[www.rioarchitects.com](http://www.rioarchitects.com)  
[@rioarchitects](https://www.instagram.com/rioarchitects)

|                                                                                      |                                                                                    |
|--------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|
| <b>Rio Cardiff</b><br>21a Allensbank Road<br>Cardiff CF14 3PN<br>+44 (0)29 2025 0066 | <b>Rio London</b><br>19 21 Hatton Garden<br>London EC1N 8BA<br>+44 (0)20 2691 7565 |
|--------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|



PROJECT TITLE :  
MRI Scanner  
Llandarcy

DRAWING TITLE :  
Existing Site Sections

DRAWN BY: RLD      CHECKED BY: JY      APPROVED BY: RR

|               |                      |
|---------------|----------------------|
| JOB NO : 0330 | SCALE : 1 : 100 @ A1 |
|---------------|----------------------|

|                 |                |              |             |            |              |                 |
|-----------------|----------------|--------------|-------------|------------|--------------|-----------------|
| SUITABILITY :   |                |              |             | S2         |              |                 |
| DATE : 22/02/22 |                | REVISION:    |             |            |              |                 |
| PROJECT<br>0330 | ORIGIN.<br>RIO | VOLUME<br>01 | LEVEL<br>XX | TYPE<br>DR | DISCIP.<br>A | NUMBER<br>90105 |