



The Coal
Authority

Resolving the **impacts** of mining

Non-Residential Coal Mining Consultants Report



49 TREFORGAN ROAD, CRYNANT, NEATH PORT TALBOT,
SA10 8PW

Date of enquiry:	27 October 2017
Date enquiry received:	27 October 2017
Issue date:	27 October 2017

Our reference:	51001641010001
Your reference:	

Non-Residential Coal Mining Consultants Report

This report is based on and limited to the records held by the Coal Authority at the time the report was produced.

Client name

William Michael Clarke

Enquiry address

49 TREFORGAN ROAD, CRYNANT, NEATH PORT
TALBOT, SA10 8PW


How to contact us

0345 762 6848 (UK)
+44 (0)1623 637 000 (International)

200 Lichfield Lane
Mansfield
Nottinghamshire
NG18 4RG

www.groundstability.com

 /company/the-coal-authority
 /thecoalauthority
 /coalauthority



Approximate position of property



Reproduced by permission of Ordnance Survey on behalf of HMSO. © Crown copyright and database right 2017. All rights reserved.

Ordnance Survey Licence number: 100020315

Detailed findings

Past underground coal mining

Colliery	Seam	Mineral	Panel	Depth (m)	Direction to working	Disposition	Extraction thickness (cm)	Year
unnamed	ABERGORCHI	Coal	4I09	175	Beneath Property	0.0	114	1976
unnamed	ABERGORCHI	Coal	4OC1	187	S	0.5	100	1975

Probable unrecorded shallow workings

None.

Outcrops

Seam name	Mineral	Thin indicator	Distance to outcrop (m)	Direction to outcrop	Bearing of outcrop
UNNAMED	Coal	False	43.7	354	84

Spine roadways at shallow depth

None recorded.

Future underground mining

None recorded.

Licence details (AOR)

None recorded.

Section 46 notices

None recorded.

Geology

No faults, fissures or breaklines recorded.

Mine entries

None recorded.

Court orders

None recorded.

Worked out opencast sites

None recorded.

Coal mining related hazards

None recorded.

Coal mining subsidence

The Coal Authority has not received a damage notice or claim for the subject property, or any property within 50 metres, since 31 October 1994.


There is no current Stop Notice delaying the start of remedial works or repairs to the property.

The Coal Authority is not aware of any request having been made to carry out preventive works before coal is worked under section 33 of the Coal Mining Subsidence Act 1991.

Enquiry boundary

Key

Approximate position of enquiry boundary shown



How to contact us

0345 762 6848 (UK)
+44 (0)1623 637 000 (International)

200 Lichfield Lane
Mansfield
Nottinghamshire
NG18 4RG

www.groundstability.com

 /company/the-coal-authority

 /thecoalauthority

 /coalauthority



Reproduced by permission of Ordnance Survey on behalf of HMSO. © Crown copyright and database right 2017. All rights reserved.

Ordnance Survey Licence number: 100020315