

Internal Photographs



(Top) Existing internal space is cluttered and floor area is inefficiently used.

(Bottom) Internal café space, with additional flat roofed storage/ staff welfare areas interrupting the internal volume

(Top) Inside the main entrance to the north with ice cream parlour to the right. Large areas given over to circulation.

(Bottom) Central café space with servery and external access door to rear of image

(Top) Kitchens

(Bottom) Existing meeting room is oddly shaped and does not provide a high quality space