McDonald's Restaurant
Store 0601 Skewen

CPS
RS
Asphalt
Conc
MH
GU
150Ø VC
HEAVY GREASE IN DRAIN
9600mm
Extension
Present Booth
Extension
Cash Booth
11000
7400mm
4500mm
1
2
3
4
5
6
ST04 50.072
ASSUMED ROUTE NOT SURVEYED
ER
8.0mh
ASSUMED ROUTE
8.0mh
Asphalt
GU
Conc
GU
ST05 49.739
9100mm
10.0mh
LP
10.0mh
PRF 1.8mh
Grass
MH
MH
MH
MH
Pavours
IC
150Ø VC.
10.0mh
Grass
NIGHT GREASE
IC
150Ø VC.
SEWER ABANDONED
32m DS FW6 DUE TO 60% GREASE IN DRAIN.
PRF 1.8mh
PRF 1.8mh
PRF 1.8mh
PRF 1.8mh
FW5 UNABLE TO LIFT. 2 x 1400mm x 700mm INFILL CONCRETE COVER
INSPECTION CHAMBER
DIMENSIONS UNKNOWN.
New External glazed door
New cranked Bollard decorated white with reflective strips
ASSUMED ROUTE NOT SURVEYED. DUE TO GREASE IN DRAIN.
SEWER ABANDONED 1-1m US FW6 DUE TO GREASE IN DRAIN
A465
FW6, 1640mm DEEP 900mm x 1200mm BRICK CHAMBER WITH 600mm x 600mm D400 COVER.
7m DS FW6 ROOT INGRESS THROUGH JOINT.

Drawing CDM/601/Sketch/Position of Sewers within Demise

NTS

#601 SKEWEN
WELSH WATER SEWER WITHIN DEMISE