

PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
19

Date:
22/01/2020

General
view of
arising
WS1.



Photo No.
20

Date:
22/01/2020

General
view failed
hand pit for
WS2. Note
concrete in
centre of pit.



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
21

Date:
22/01/2020

General view of arisings from WS2. Note liner split during drilling.



Photo No.
22

Date:
22/01/2020

General view failed hand pit for WS3. Note concrete in centre of pit



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
23

Date:
22/01/2020

General view of arisings from WS3 between 1.2m and 2.2m.



Photo No.
24

Date:
22/01/2020

General view of arisings from WS3 between 2.2m and 3.2m

