

PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
3

Date:
21/01/2020

General view
of site facing
southwest
from
northeast
portion



Photo No.
4

Date:
21/01/2020

General view
of site facing
northwest
from
southeast
portion



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
5

Date:
21/01/2020

General view of area in central portion showing paved pathway. Bike shed and pathway were in constant use. Services indicated underlying slabs.



Photo No.
6

Date:
21/01/2020

General view of western portion of site. Further live services identified showing to cross pathway



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
7

Date:
21/01/2020

Further view of walkway in western portion with potential service identified in the bottom centre of picture.



Photo No.
8

Date:
21/01/2020

General view of area in northern portion. Numerous visible services and further service running close to base of slope (BT)



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
9

Date:
21/01/2020

Further view of western portion with potential service identified trending across the soft landscaping.



Photo No.
10

Date:
21/01/2020

General view of area in southern portion with services identified underlying the gravel surface

