

PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
11

Date:
21/01/2020

View along southern wall of ESRI building showing 2No drainage runs north of the site.



Photo No.
12

Date:
21/01/2020

Services identified in southwest portion.



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
13

Date:
21/01/2020

General view of TP1. Note membrane and coarse gravel/cobble limestone.



Photo No.
14

Date:
21/01/2020

View of arisings from TP1.



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
15

Date:
21/01/2020

General
view of
infiltration
test in TP2.



Photo No.
16

Date:
21/01/2020

General
view of
arising
from TP2



PHOTOGRAPHIC LOG

Site Location: Swansea University Bay Campus, Swansea

Photo No.
17

Date:
21/01/2020

General
view of
infiltration
test in TP3.



Photo No.
18

Date:
21/01/2020

General
view of
arising
from TP3

