

2/22/2021

Survey Report

Survey Report - 22 February 2021 by Ian Bain



Project Details

Project Address: 33 Church Street, Pontardawe, Swansea, West Glamorgan, SA8 4JB

Client Name: Charter Homes Land Limited

Client Number:

Client Email Address:

Survey Details

Temperature: Normal range

Weather Conditions: Damp

Surveyor Comments:

Called on site to witness commencement of works. New inspection chamber installed along with associated pipes.

Survey Images



New inspection chamber