



Contamination Risk PASSED

Professional Opinion

RPS Consultants have passed this report in accordance with the definition of contaminated land within Part 2A of the Environmental Protection Act 1990. Please refer to the Professional Opinion page and Section 1 for further information.



Flood Risk: None Identified

Refer to Section 2 for further information

Conveyancer Guidance

While this report may have identified areas at risk of flooding on or within 250m of the subject property, the extent and frequency of these potential flood events present a low risk. Please refer to Section 2 for further information.



Radon: IDENTIFIED

Refer to Section 3 for further information



Ground Stability: IDENTIFIED

Refer to Section 4 for further information



Other Influential Factors:

Refer to Section 5 for further information

Environmental Constraints: IDENTIFIED

See Section 5a

Report issued for the property at

**Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA**

Report Reference
52716788_1_1

National Grid Reference
275190 206560

Customer Reference
945122_510681_HCP

Report Date
27 January 2014

Requested by
**Property Information Exchange Ltd
Wyvols Court
Swallowfield
Berkshire
RG7 1WY**

Contact Details

If you require assistance please contact your Search Provider or phone Customer Services on 0844 844 9966 or email helpdesk@homecheck.co.uk

Landmark Contribution

By purchasing this report, the report recipient may be eligible for Remediation Contribution of up to £60,000 if served with a Remediation Notice by the Local Authority. Such a notice forces the homeowner to contribute to the costs of remediating the site. For more information see Landmark's Terms and Conditions.



Professional Opinion

Contamination Risk

PASSED

In the professional opinion of RPS Consultants, the level of contamination risk associated with the information disclosed in the Homecheck Professional report dated 27th January 2014 and reference 52716788_1_1, 945122_510681_HCP for

**Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA**

1) is unlikely that the property would be designated "contaminated land" within the meaning of Part 2A of the Environmental Protection Act 1990.

2) is unlikely to have an adverse effect on the security of the property for normal lending purposes.

The professional opinion refers to Section 1 of this report and should always be read in conjunction with the full text of that report. No physical site inspection or survey has been carried out or is proposed.

A 'Guide to the RPS Professional Opinion / Certificate' can be found at the back of the report.

Approved by

RPS Environmental Risk Team

RPS

Contents and Summary of Findings



Site Location



Section 1: Contamination Risk Findings

Contamination Risk	0-25m	25-250m	250-500m	See Section
Designated Contaminated Land	No	No	No	1a
Landfill and Waste	No	Yes	Yes	1b
Potentially Contaminative Activities	No	Yes	Yes	1c
Known Pollution Incidents	No	No	No	1d
Other Potential Contaminative Land Uses	No	Yes	n/a	1e



Section 2: Flood Findings

Flood	0-25m	25-250m	See Section
River Flooding	No	Yes	2a
Coastal Flooding	No	No	2b
Surface Water Flooding	No	Yes	2c



Section 3: Radon Findings

Radon	Result	See Section
Radon Affected Property	Yes	3



Section 4: Ground Stability Findings

Ground Stability	Result	See Section
Man-Made Factors	Yes	4a
Natural Factors	Yes	4b



Section 5: Other Influential Factors

Other Influential Factors	Result	See Section
Environmental Constraints	Yes	5a



Site Location



Aerial Photograph

The photograph below shows the location of the site to which this report relates.



Homecheck® Report

Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA


Report Reference 52716788_1_1

©Copyright 2014, Landmark Information Group Ltd
All rights reserved
Date 27 January 2014
Page 2 of 25



Location Map

The map below shows the location of the site to which this report relates.



Homecheck® Report

Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA

Report Reference 52716788_1_1

©Copyright 2014, Landmark Information Group Ltd
All rights reserved
Date 27 January 2014
Page 3 of 25



Section 1: Contamination Risk Findings

The whole of section 1 deals with potential sources of contamination and provides the information by which this report has either been passed or referred for assessment.



Section 1a and 1b: Information Map

The map detailed below shows the location of the Designated Contaminated Land and Landfill and Waste features highlighted within sections 1a and 1b of this report.



© Crown copyright. All Rights Reserved. Licence Number: 100022432

Section 1a

- Contaminated Land Registry Entries and Notices

Section 1b

- Registered Landfill Sites
- Registered Landfills (Potential Buffer)
- BGS Recorded Landfill Sites
- Local Authority Recorded Landfill Sites
- Historical Landfill Sites
- Permitted Waste Sites - Authorised Landfill Site Boundaries
- Environmental Permitting Regulations - Waste
- Integrated Pollution Control Registered Waste Sites
- Registered Waste Treatment or Disposal Sites
- Registered Waste Transfer Sites

Homecheck® Report

Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA

Report Reference 52716788_1_1

©Copyright 2014, Landmark Information Group Ltd
All rights reserved
Date 27 January 2014
Page 4 of 25

Section 1a: Designated Contaminated Land

The data within this section tells you whether your property or surrounding area has been identified by the Local Authority as "Contaminated Land" under the Environmental Protection Act 1990. Should there be an indication of contamination, it is not necessarily a cause for concern. Your report will be assessed by our professional environmental consultants who will advise you what, if any, considerations need to be made should you proceed with the property purchase.

Enquiry	Result
Has any contaminated land been identified within 500m of the property?	No

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

Contaminated Land Register Entries and Notices

No factors identified for this property

Section 1b: Landfill and Waste

The information in this section is telling you about active and historic landfill and waste sites within 500 metres of the property. Having a landfill or waste site near your property does not necessarily mean that you or the property will be affected. However, it is something you need to be aware of, because landfill and waste can have a detrimental effect on the surrounding environment, house value and health. A closed landfill/waste site should be given equal consideration to an active site, because of landfill by-products. For instance, landfill with lots of organic material can continue to produce odours and gas for many years.

Enquiry	Result
Have any landfill and waste sites been identified within 500m of the property?	Yes

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

Registered Landfill Sites

No factors identified for this property

BGS Recorded Landfill Sites

No factors identified for this property

Local Authority Recorded Landfill Sites

No factors identified for this property

Local Authority Recorded Landfill Coverage

The following list details the Local Authorities that cover the search area who have made landfill data available:

Neath Port Talbot County Borough Council	- Has supplied landfill data	5
---	-------------------------------------	---

For further information regarding the availability of Local Authority Recorded Landfill data you may wish to forward enquiries to one or more of the contacts indicated above.

Historical Landfill Sites

1	Name: Tip off A4067 at Godre r-graig Reference: EAHLD34827	Godre Graig, Ystalefera	Specified Waste Type: Not Supplied Date of Issue: Not Supplied First Input Date: Not Supplied Last Input Date: Not Supplied Boundary Quality: As Supplied Positional Accuracy: Positioned by the supplier	69m	1
---	---	-------------------------	--	-----	---

Map ID	Reference	Location	Details	Distance	Contact
2	Name: Disused Tip of A4067 Reference: EAHL34817	Godrer-graig, Port Talbot	Specified Waste Type: Not Supplied Date of Issue: Not Supplied First Input Date: Not Supplied Last Input Date: Not Supplied Boundary Quality: As Supplied Positional Accuracy: Positioned by the supplier	69m	1
3	Name: Cilmaengwyn Waste Tip Reference: EAHL34816	Cilmaegwyn	Specified Waste Type: Not Supplied Date of Issue: Not Supplied First Input Date: Not Supplied Last Input Date: Not Supplied Boundary Quality: As Supplied Positional Accuracy: Positioned by the supplier	297m	1

Permitted Waste Sites - Authorised Landfill Site Boundaries

No factors identified for this property

Environmental Permitting Regulations - Waste

No factors identified for this property

Integrated Pollution Control Registered Waste Sites

No factors identified for this property

Registered Waste Treatment or Disposal Sites

No factors identified for this property

Registered Waste Transfer Sites

No factors identified for this property


Next Steps

If you would like any further information in respect of the above findings we recommend that you get in touch with those listed in the 'Useful Contacts' section. Each contact reference shown in the above table relates to detailed contact information contained near the back of this report. Further information is also available in the 'Useful Information' section.



Section 1c and 1d: Information Map

The map detailed below shows the location of the Potentially Contaminative Activities and Known Pollution Incidents features highlighted within sections 1c and 1d of this report.



© Crown copyright. All Rights Reserved. Licence Number: 100022432

Section 1c

- | | |
|---|---|
| ▲ Local Authority Pollution Prevention and Controls | ✕ Radioactive Substances Register |
| ▼ Local Authority Integrated Pollution Prevention and Control | ✕ Planning Hazardous Substance Consents |
| ▶ Integrated Pollution Controls | ✕ Control of Major Accident Hazards Sites (COMAH) |
| ▶ Environmental Permitting Regulations - Industry | ✕ Notification of Installations Handling Hazardous Substances (NIHHS) |
| ◆ Consent to Discharge to Controlled Waters | ★ Explosive Sites |

Section 1d

- | |
|---|
| + Local Authority Pollution Prevention and Control Enforcements |
| + Enforcement and Prohibition Notices |
| + Planning Hazardous Substance Enforcements |
| ● Prosecutions Relating to Authorised Processes |
| ● Environmental Pollution Incidents |
| ● Prosecutions Relating to Controlled Waters |

Homecheck® Report

Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA

Report Reference 52716788_1_1

©Copyright 2014, Landmark Information Group Ltd
All rights reserved
Date 27 January 2014
Page 7 of 25

Section 1c: Potentially Contaminative Activities

This section describes current and historic licensed activities within 500 metres of the property, which have the potential to cause contamination or have an impact on the environment. The licensed activities could range from pollution to air, land or water; storage or disposal of radioactive substances; or storage of hazardous or explosive materials. Licences may no longer be active, but the nature of the past activity means it could still have an impact.

Enquiry	Result
Have any potentially contaminative activities been identified within 500m of the property?	Yes

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

Local Authority Pollution Prevention and Controls

No factors identified for this property

Local Authority Integrated Pollution Prevention And Control

No factors identified for this property

Integrated Pollution Controls

No factors identified for this property

Environmental Permitting Regulations - Industry

No factors identified for this property

Consent to Discharge to Controlled Waters

4	Name: Prichard B Reference: Bc0021801	Cwmtawe Isaf Godregraig Swansea	Type: Unknown Discharge Discharge Type: Unspecified Property Type: Livestock Production, Food Production Discharge Environment Type: Coastal Receiving Water: Catch Pit To R/Bank Swansea Va Status: Consent expired Date of Issue: 23rd December 1964 Positional Accuracy: Located by supplier to within 100m	181m	1
5	Name: Lliw Valley Borough Council Reference: Bp0009901	Pontardawe Tareni Site Godre-Graig Tareni Site Godre-Graig Swansea Godre-Graig Swansea W Glam	Type: Unknown Discharge Discharge Type: Unspecified Property Type: Undefined Or Other Discharge Environment Type: Freshwater Stream/River Receiving Water: River Tawe Status: Consent expired Date of Issue: 7th February 1986 Positional Accuracy: Located by supplier to within 100m	217m	1

Map ID	Reference	Location	Details	Distance	Contact
6	Name: Dwr Cymru Cyfyngedig Reference: BW2302801	Swo. Godre'R Graig Soc 20. Godre'R Godre'R Graig Ystalyfera Neath Port Talbot	Type: Unknown Discharge Discharge Type: Unspecified Property Type: Sewerage Network - Sewers - Water Company Discharge Environment Type: Freshwater Stream/River Receiving Water: River Tawe Status: New Consent, by Application (Water Resources Act 1991, Section 88) Date of Issue: 20th October 1989 Positional Accuracy: Located by supplier to within 100m	288m	1
7	Name: Dwr Cymru Cyfyngedig Reference: Bp0343701	Swo. Godre'R Graig Soc 20. Godre'R Godre'R Graig Ystalyfera Neath Port Talbot	Type: Sewerage Discharge Discharge Type: Public Sewage: Storm Sewage Overflow Property Type: Sewerage Network - Sewers - Water Company Discharge Environment Type: Freshwater Stream/River Receiving Water: River Tawe Status: Consent without application (Water Resources Act 1991, Schedule 10) Date of Issue: 7th March 2005 Positional Accuracy: Located by supplier to within 10m	288m	1
8	Name: Dwr Cymru Cyfyngedig Reference: Bw2302801	Swo. Godre'R Graig Soc 20. Godre'R Godre'R Graig Ystalyfera Neath Port Talbot	Type: Sewerage Discharge Discharge Type: Public Sewage: Storm Sewage Overflow Property Type: Sewerage Network - Sewers - Water Company Discharge Environment Type: Freshwater Stream/River Receiving Water: River Tawe Status: New Consent (Water Resources Act 1991, Section 88 & Schedule 10 as amended by Environment Act 1995) Date of Issue: 20th May 2005 Positional Accuracy: Located by supplier to within 10m	288m	1
9	Name: Mr Oswald Davies Reference: BF0102701	191 Graig Rd Godrergrraig Ystalyfera Godrergrraig Ystalyfera Swansea	Type: Unknown Discharge Discharge Type: Unspecified Property Type: Domestic Property (Single) Discharge Environment Type: Into Land Receiving Water: To Land Nr Swansea Canal Status: New Consent, by Application (Water Resources Act 1991, Section 88) Date of Issue: 12th December 1973 Positional Accuracy: Located by supplier to within 100m	310m	1

Map ID	Reference	Location	Details	Distance	Contact
10	Name: Lliw Valley Borough Council Reference: Bp0009902	Pontardawe Tareni Site Godre-Graig. Tareni Site Godre-Graig, Swansea Godre-Graig, Swansea W Glam	Type: Unknown Discharge Discharge Type: Unspecified Property Type: Undefined Or Other Discharge Environment Type: Freshwater Stream/River Receiving Water: River Tawe Status: Consent expired Date of Issue: 7th February 1986 Positional Accuracy: Located by supplier to within 100m	313m	1
11	Name: Lliw Valley Borough Council Reference: Bp0025201	Swansea Tareni Site Area B	Type: Unknown Discharge Discharge Type: Unspecified Property Type: Undefined Or Other Discharge Environment Type: Freshwater Stream/River Receiving Water: River Tawe Status: New Consent (Water Resources Act 1991, Section 88 & Schedule 10 as amended by Environment Act 1995) Date of Issue: 7th October 1986 Positional Accuracy: Located by supplier to within 10m	396m	1

Radioactive Substances Register

No factors identified for this property

Planning Hazardous Substance Consents

No factors identified for this property

Control of Major Accident Hazards Sites (COMAH)

No factors identified for this property

Notification of Installations Handling Hazardous Substances (NIHHS)

No factors identified for this property

Explosive Sites

No factors identified for this property

Next Steps

If you would like any further information in respect of the above findings we recommend that you contact the relevant Local Authority or the Environment Agency, their contact details can be found in the 'Useful Contacts' section of this report. Further Information is also available in the 'Useful Information' section.

Section 1d: Known Pollution Incidents

The data within this section describes unpermitted activity in your area (e.g. polluting incidents, or exceedance of permitted allowance) where the activity led to a prosecution or enforcement of regulations. Whilst all of these records are historic, the nature of the incident may have long term effects.


Enquiry	Result
Have any known pollution incidents been identified within 500m of the property?	No

Map ID	Reference	Location	Details	Distance	Contact
Local Authority Pollution Prevention and Control Enforcements					
No factors identified for this property					
Enforcement and Prohibition Notices					
No factors identified for this property					
Planning Hazardous Substance Enforcements					
No factors identified for this property					
Prosecutions Relating to Authorised Processes					
No factors identified for this property					
Environmental Pollution Incidents					
No factors identified for this property					
Prosecutions Relating to Controlled Waters					
No factors identified for this property					



Section 1e: Information Map

The map detailed below shows the location of the Other Potential Contaminative Land Uses features highlighted within section 1e of this report.



© Crown copyright. All Rights Reserved. Licence Number: 100022432

- | | |
|--|---|
| ✕ Fuel Station Entries | ☑ ▲ —●— Potentially Infilled Land (Non-Water) |
| ★ Contemporary Trade Directories | ☐ ▲ —●— Potentially Infilled Land (Water) |
| ✚ Former Marshes | ■ ● —○— Potentially Contaminative Industrial Uses (Past Land Use) |
| ▼ Historical Tanks and Energy Facilities | |

Section 1e: Other Potential Contaminative Land Uses

This section describes either current or historic activity, which could be considered to be contaminative. This section makes no statement about whether the activity requires a licence; however our environmental experts deem that the activities described in this section could lead to potential contamination. The information is taken from a variety of sources including trade directories, Landmark's extensive historical map collection and analysis of historic activity. Records are highlighted due to the potential for contamination to exist.

Enquiry	Result
Have any other potential sources of contamination been identified within 250m of the property?	Yes

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

Fuel Station Entries

No factors identified for this property

Contemporary Trade Directory Entries

12	Name: Swansea Valley Exhaust & Tyre Centre	Gnoll Rd Godrergraig Swansea West Glamorgan SA9 2PA	Classification: Tyre Dealers Status: Active Positional Accuracy: Manually positioned to the road within the address or location	208m	-
----	---	---	--	------	---

Former Marshes

No factors identified for this property

Potentially Infilled Land (Non-Water)

No factors identified for this property

Potentially Infilled Land (Water)

13	Not Supplied	Not Supplied	Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Map Published Date: 1953	184m	-
14	Not Supplied	Not Supplied	Unknown Filled Ground (Pond, marsh, river, stream, dock etc) Map Published Date: 1965	231m	-

Potentially Contaminative Industrial Uses (Past Land Use)

15	Not Supplied	Not Supplied	Class: Heap, unknown constituents Map Published Date: 1953 - 1984	69m	-
16	Not Supplied	Not Supplied	Class: Heap, unknown constituents Map Published Date: 1953 - 1965	77m	-
17	Not Supplied	Not Supplied	Class: Mineral railway Map Published Date: 1921 - 1953	89m	-
18	Not Supplied	Not Supplied	Class: Heap, unknown constituents Map Published Date: 1921	118m	-
19	Not Supplied	Not Supplied	Class: Railways Map Published Date: 1965	161m	-
20	Not Supplied	Not Supplied	Class: Mining of coal & lignite Map Published Date: 1921 - 1953	162m	-
21	Not Supplied	Not Supplied	Class: Mineral railway Map Published Date: 1921	199m	-
22	Not Supplied	Not Supplied	Class: Sewage Map Published Date: 1921 - 1965	199m	-

Map ID	Reference	Location	Details	Distance	Contact
Historical Tanks And Energy Facilities					
23	Not Supplied	Not Supplied	Type: Potential Tanks Positional Accuracy: Positioned to location of cartographic text Date of Mapping: 1972	73m	-
24	Not Supplied	Not Supplied	Type: Electrical Sub Station Facilities Positional Accuracy: Positioned to location of cartographic text Date of Mapping: 1972	231m	-

Next Steps

If you would like any further information in respect of the above findings we recommend that you contact our Customer Services Team, whose details can be found in the 'Useful Contacts' section of this report. Further Information is also available in the 'Useful Information' section.




Section 2: Flood Findings

The whole of this section deals with potential sources of flooding that may impact the property.



Section 2a and 2b: River and Coastal Flood Map


The map detailed below shows the location of potential river and coastal flood risk. The potential risk has been modelled on the basis of an event occurring on average every 75, 200 or 1000 years.






Section 2c: Surface Water Flood Map

The map detailed below shows the location of potential surface water flood risk. The potential risk has been modelled on the basis of an event occurring on average every 75, 200 or 1000 years.



© Crown copyright. All Rights Reserved. Licence Number: 100022432

Surface Water Flooding



Homecheck® Report

Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA

Report Reference 52716788_1_1

©Copyright 2014, Landmark Information Group Ltd
All rights reserved
Date 27 January 2014
Page 16 of 25

Section 2a: River Flooding

River flooding mainly happens when the river catchment (that is the area of land that feeds water into the river and the streams that flow into the main river) receives greater than usual amounts of water (for example through rainfall or melting of snow). The amount of runoff depends on the soil type, catchment steepness, drainage characteristics, agriculture and urbanisation as well as the saturation of the catchment. The extra water causes the level of the water in the river to rise above its banks or retaining structures.

Enquiry	Result	Contact
Is there a potential risk of river flooding within 250m of the property?	Yes	-

Section 2b: Coastal Flooding

Coastal flooding is the inundation of land areas along the coast caused by sea water rising above normal tidal conditions. Coastal flooding can arise from a combination of high tides, wind induced tidal surge, storm surge created by low pressure and wave action.

Enquiry	Result	Contact
Is there a potential risk of coastal flooding within 250m of the property?	No	-

Section 2c: Surface Water Flooding

Surface water flooding results from rainfall running over ground before entering a watercourse or sewer. It is usually associated with high intensity rainfall events (typically greater than 30mm per hour) but can also occur with lower intensity rainfall or melting snow where the ground is already saturated, frozen, developed (for example in an urban setting) or otherwise has low permeability.

Enquiry	Result	Contact
Is there a potential risk of surface water flooding within 250m of the property?	Yes	-

Next Steps

In order to gain more detailed information on the type and likelihood of your property being impacted by a flood event, and the potential impact on insurance, we recommend that you purchase our Homecheck Professional Flood Report.

If you would like more information please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email **helpdesk@homecheck.co.uk**.

Flood data provided by Jeremy Benn Associates Limited. © Copyright Jeremy Benn Associates Limited & JBA Risk Management Limited 2008-2014



Section 3: Radon Findings

The information within this section tells you whether the property is located in a radon affected area. Radon is a radioactive gas which occurs naturally in rocks and soils. You cannot see, hear, feel or taste it. Exposure to particularly high levels of radon may increase the risk of developing lung cancer, and is therefore something you need to be aware of or should consider.

Enquiry	Result	Contact
Is the property within 25m of a radon affected area?	The property is in a radon affected area, as between 1 and 3% of homes are above the action level	2
What level of radon protection measures for new dwellings or extensions to existing ones is required for the area within 25m of the property?	No radon protective measures are necessary in the construction of new dwellings or extensions	2

Next Steps

The level of radon concentration can only be established by having the building tested. Action should be taken if the indoor radon level is measured and found to be above 200 becquerel's per cubic meter. If you would like any further information we recommend you contact Public Health England whose details can be found in the 'Useful Contacts' section of this report.

Further Action

Airtech Environmental Systems can advise on radon testing kits, which cost £39.36 including VAT and can run from 7 days to 3 months. They also have a team of surveyors on hand to provide recommendations and advice for any properties above the target level of 100 becquerel's per cubic meter or action level of 200 becquerel's per cubic meter. Airtech Environmental Systems can provide a report, recommendations and a quotation for any recommended works. For more detailed information please call their free-phone number 0800 378017.



Section 4: Ground Stability Findings

This section provides summary information on factors that could affect the ground stability of the property. It considers both man-made factors (e.g. mining activity) and natural hazards (e.g. geological stability).

Section 4a: Man-Made Factors

Enquiry	Result	Contact
Is the property within 25m of a Coal Mining Affected Area?	Yes	3
Comment: The property is in an area which may be affected by Coal Mining activity. It is recommended that a Coal Mining report is obtained from the Coal Authority.		

Next Steps

This section has highlighted that the property is in a coal mining affected area. We recommend that you purchase a Coal Mining Report from the Coal Authority. Please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email helpdesk@homecheck.co.uk.

Section 4b: Natural Factors

Enquiry	Result	Contact
What is the potential for natural ground instability in the area within 50m of the property?	Moderate	-
Comment: The BGS indicate that there is a moderate potential for natural ground instability in the search area. This does not necessarily mean there is cause for concern in terms of property stability, however we recommend that specific advice be commissioned from a qualified member of the RICS.		

Next Steps

This section has highlighted that ground stability is an area of concern, meaning that your property may be affected by subsidence or land-heave. If you would like any further information in respect of the above findings we recommend that you purchase our Ground Stability Report. Please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email helpdesk@homecheck.co.uk.



Section 5: Other Influential Factors

The following section provides information on a variety of factors which may have an influence on the property or surrounding area.



Section 5a: Environmental Constraints

Enquiry	Result
Is the property within 250m of an area likely to be impacted by Environmental Constraints?	Yes

Map ID	Reference	Location	Details	Distance	Contact
--------	-----------	----------	---------	----------	---------

Areas of Outstanding Natural Beauty

No factors identified for this property

Local Nature Reserves

Name: Swansea Canal	N/A	Total Area (m2): 35620.33	60m	4
Reference: Not Given		Designated Date: 31st December 1987		

National Nature Reserves

No factors identified for this property

National Parks

No factors identified for this property

Ramsar Sites

No factors identified for this property

Sites of Special Scientific Interest

No factors identified for this property

Special Areas of Conservation

No factors identified for this property

Special Protection Areas

No factors identified for this property

Next Steps

If you would like any further information in respect of the above findings we recommend that you get in touch with those listed in the 'Useful Contacts' section of this report. Each contact reference shown in the above table relates to detailed contact information contained within the back of this report.

Useful Contacts

Contact 1 - Environment Agency - National Customer Contact Centre (NCCC)

PO Box 544	Tel: 08708 506 506	enquiries@environment-agency.gov.uk
Templeborough		
Rotherham		
S60 1BY		

Contact 2 - Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards

Chilton	Tel: 01235 822622	radon@phe.gov.uk
Didcot	Fax: 01235 833891	www.ukradon.org
Oxfordshire		
OX11 0RQ		

Contact 3 - The Coal Authority - Mining Report Service

200 Lichfield Lane	Tel: 0845 7626848	thecoalauthority@coal.gov.uk
Mansfield		
Nottinghamshire		
NG18 4RG		

Contact 4 - Neath Port Talbot County Borough Council

Civic Centre	Tel: 01639 763333	www.neath-porttalbot.gov.uk
Port Talbot	Fax: 01693 763444	
West Glamorgan		
SA13 1PJ		

Contact 5 - Neath Port Talbot County Borough Council - Environmental Health Department

Room 322	Tel: 01639 763333	www.neath-porttalbot.gov.uk
Neath Civic Centre	Fax: 01693 763444	
Neath		
West Glamorgan		
SA11 3QZ		

Landmark Information Group Limited

Legal and Financial	Tel: 0844 844 9966	helpdesk@homecheck.co.uk
Imperium	Fax: 0844 844 9980	www.landmarkinfo.co.uk
Reading		
Berkshire		
RG2 0TD		

The Landmark website contains links to many of our data suppliers which may prove useful.

Please note that the Environment Agency/SEPA have a charging policy in place for enquiries.

Landmark works in association with:



THE
COAL
AUTHORITY



Report Version: HCP v1.0.4.5

Homecheck® Report

Plot adjacent to 42
Gnoll Road
Godrergraig Swansea
SA9 2PA

Report Reference 52716788_1_1

©Copyright 2014, Landmark Information Group Ltd
All rights reserved
Date 27 January 2014
Page 22 of 25

Useful Information

The following explanatory notes may be of assistance to users of the Homecheck Professional report. Practitioners are reminded that full guidance notes are contained in the Practitioners Guide.

Professional Opinion

A Professional Opinion in relation to Part 2A of the Environmental Protection Act 1990 is provided by RPS Consultants. In many cases the report will be PASSED without referral. However, in some cases, entries that may be of concern are revealed by the search, in which case the report is REFERRED free of charge for more detailed consideration, although this will not include a physical site inspection. After such referral the report may be PASSED or suggestions made of some FURTHER ACTION that could be taken, in the form of questions to ask of the appropriate authorities. When responses to these questions are received it is the responsibility of the client and their professional advisors to decide if they are happy to proceed.

Flood Risk

A limited flood risk screening exercise is included in this report designed to satisfy basic flood risk screening due diligence including consideration of river, coastal and surface water flooding. Where a potential flood risk is "Identified" you may wish to consider commissioning a more detailed flood risk screening report. When there is "None Identified" this does not indicate that there is not risk of flooding at the property, but that the risk of flooding from the sources screened (river, coastal and surface water) within the vicinity of the property is such that the risk may not be considered significant.

Location Map

The Ordnance Survey location map may show features which are not necessarily otherwise included in this report. You are advised to supplement the information contained in the report with the descriptive text shown on the map.

Positional Accuracy

We locate data in a variety of ways according to information provided to us and subsequent in-house research. If data is provided as a point on the ground, we provide a "positional accuracy" which tells you how confident we are of the actual location.

Section 1b: Landfill and Waste

At present no complete national data set exists for landfill site boundaries, therefore, a point grid reference, provided by the data supplier, is used for some landfill sites. In certain cases the point grid references supplied provide only an approximate position, and can vary from the site entrance to the centre of the site. Where the exact position of the site is unclear for Registered Landfill data, Landmark construct either a 100 metre or 250 metre "buffer" around the point to warn of the possible presence of landfill. The size of this "buffer" relates to the positional accuracy that can be attributed to the site. The "buffer" is shown on the map as a red hatched area. For further information regarding landfill sites identified in the report, please contact the relevant agency or authority referenced in the Useful Contacts section.

The BGS holds records of over 3,000 landfill sites that accepted waste prior to the Control of Pollution Act (COPA) 1974. These were not subject to any strict regulation or monitoring.

Permitted Waste Sites and Environmental Permitting Regulations - Waste cover current or recently current consents issued for landfill sites, waste transfer, treatment or disposal sites by the Environment Agency, under Section 64 of the Environmental Protection Act 1990 (Part 2) and prescribed by regulation 10 of SI No. 1056 of the Waste Management Licensing Regulations 1994.

Section 1c: Potentially Contaminative Activities

Identified discharge consents could be for storm water discharges, soakaways or septic tanks.

If a radioactive substance licence has been identified the consent band will be given under enquiries and replies. Consents fall into one of four bands: Band 1 and 2 Nuclear licensed sites authorised by the Nuclear Installations Inspectorate e.g. nuclear power stations Band 3 Site registered/authorised to accumulate and dispose of radioactive materials, only non-nuclear operations are carried out on site e.g. hospitals Band 4 Sites registered to keep and use radioactive material e.g. laboratories, universities, commercial premises using appliances such as monitoring equipment, alarm systems, tritium lighting etc.

Data supplied for Explosive Sites, Control of Major Accident Hazards Sites (COMAH) and Notification of Installations Handling Hazardous Substances (NIHHS) contains public sector information published by the Health and Safety Executive and licensed under the Open Government Licence.

Section 1e: Other Potential Contaminative Land Uses

This section relates to categories of potentially contaminative land uses that have been identified by the analysis of selected Ordnance Survey historical mapping. The published date (range of dates) of the map (s) and the distance from the centre of search to the nearest point of the feature is given. Further details of the extent of the site or its activities are not available. Should you wish to examine the Ordnance Survey maps these are normally available for public inspection at the local archive or local major library. Alternatively, extracts of editions of Ordnance Survey maps are available on www.old-maps.co.uk

Potentially infilled land has been identified when a 'cavity' (a hole made by an extractive industry or natural occurrence e.g. pond) was indicated on a historic map but there was no evidence of its existence in the last available map for the area. No details of what may have been used to fill the cavity or exactly when or if it was filled are available from the mapping.

The point locations of historical tanks and energy facilities are identified from the text on Ordnance Survey 1:1250 and 1:2500 scale mapping published between 1943 and 1996, based upon a predetermined list of abbreviations, e.g. El Sub (Electricity Sub-station) and F Stn (Filling Station). The position of the point has been located at the centre of the identified text so that it would be within approximately 30 meters of the feature it was describing. The features themselves are related to energy and petroleum storage and cover the following: tanks, petrol storage, potential tanks (at depots etc.), electricity sub stations and related features, gas and gas monitoring related features, oil related features and miscellaneous power features. NB: It should be noted that the Ordnance Survey abbreviation for tank (tk) is the same as that for tracks. Therefore some of the captured text may relate to tracks and not tanks when the exact nature of the feature is not clear from the mapping.

Section 2: Flood Findings

Sections 2a, b and c of the report provide data on modelled extents of river, coastal and surface water flooding generated by JBA Consulting, a market leader in flood risk assessment commonly engaged by insurers to assess flood risk. The data has been modelled for several perils or return periods: 1 in 75, 1 in 200 or 1 in 1000 which relate to areas with a 1.3%, 0.5% and 0.1% annual probability of flooding in any one year respectively. Properties at risk of flooding during a 1 in 75 year event are typically considered to be at a high risk of flooding. The data has been generated to provide a UK wide screening tool and as a result may have inherent limitations. In addition, there may be areas of the country which are modelled to varying degrees of accuracy based on currently available topographical information.

Section 3: Radon Findings

Due to the nature of way the information is gathered, your property/site may have more than one probability of radon attributed to it. We report the worst case scenario on the property/site you have provided. This information is an estimate of the probability that a property /site in Great Britain is at or above the "Action Level" for radon (the level at which Public Health England recommends that radon levels should be reduced, those with an average of 200 Bq m⁻³ or more). This information satisfies CON29 Standard Enquiry of Local Authority; 3.13 Radon Gas: Location of the Property in a Radon Affected Area. Where the property/site is a new build, this information provides information on the level of protection required for new buildings under BR211 (Scivyer, 2007) Radon: Guidance on protective measures for new buildings.

Disclaimer: "Some of the responses contained in this section are based on data and information provided by the Natural Environment Research Council (NERC) or its component bodies the British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither NERC, BGS nor Public Health England where applicable, gives any warranty, condition or representation as to the quality, accuracy or completeness of such information and all liability (including liability for negligence) arising from its use is excluded to the fullest extent permitted by law."

Section 5a: Environmental Constraints

The Local Nature Reserves national dataset is "indicative" not "definitive". Definitive information can only be provided by individual local authorities and you should refer directly to their information for all purposes that require the most up to date and complete dataset.

General

If after reading the details in this report regarding the sites identified, you still require further information, please contact the relevant agency or authority indicated in the Useful Contacts section quoting the corresponding reference given in the text of the report.

The contacts in the Useful Contacts section may be able to provide further information relating to items identified in the report, however they are not in a position to advise how these might affect the value of a property. The findings of the report should be discussed with your professional advisor.

The Purpose and Scope of the Report

The report is designed to satisfy the concerns raised by the Law Society warning card and has been prepared to assist conveyancing professionals who may be advising clients when they sell or buy a property, obtain a mortgage, seek further mortgage advice, or commence any building works. It is designed to bring information to their attention and help them decide whether they need to seek any further specialist advice. As the report is so detailed, this information can cause concern, but professional advisors will see that further action is suggested on all issues that have been identified.

Limitations

This report has been published by Landmark Information Group Limited ("Landmark") and is supplied subject to our Terms and Conditions of Business, which are attached at the back of the report. It has been prepared on the understanding that it is to be used for an individual residential property transaction and should not be used or relied upon in a commercial property transaction. This report is neither a guarantee of the physical condition of the subject property nor a substitute for any physical investigation or inspection. The information in Homecheck Professional is derived from a number of statutory and non-statutory sources (see The Practitioner Guide for details). Whilst every effort is made to ensure the details in the report are correct, Landmark cannot guarantee the accuracy or completeness of such information or data, nor identify all the factors that may be relevant. If you are a private individual using this report Landmark recommends that you discuss its contents in full with your professional advisor. The methodology for risk assessment and the conclusions drawn therefrom are the responsibility of RPS Consultants.

Insurance

Houses registered between 1st April 1999 and 31st December 2002 and covered by the NHBC Buildmark scheme probably have insurance against certain costs if contamination occurs within ten years of their construction. From 1st January 2003, NHBC will only provide this cover if building control has been carried out by NHBC Building Control Services Limited.

Landmark Standard Terms and Conditions

Full Terms and Conditions can be found on the following link: <http://www.landmarkinfo.co.uk/Terms/Show/515>

If you experience difficulties accessing our Terms and Conditions, please copy and paste the link directly into your browser, you will then be able to access our Terms and Conditions from there. Should you still experience difficulties, please telephone our Customer Service Team on 0844 844 9966.

Copyright Statement

The data supplied for this Homecheck Professional report falls under the following copyrights: © Landmark Information Group and/or its Data Suppliers 2014; © Environment Agency and database right 2014; ©Experian Ltd 2014; Produced in whole or in part under licence from, and based in whole or in part from copyright material of © Thomson Directories Limited; © The Coal Authority owns the copyright to this data and the coal mining information used to produce it; © Peter Brett Associates LLP 2014; © Ofcom copyright 2014; © Natural England 2014 material is reproduced with the permission of Natural England, <http://www.naturalengland.org.uk/copyright>; © Countryside Council for Wales. All rights reserved; Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right 2014; © HS2 Ltd and licensed under the Open Government Licence.



Guide to the RPS Professional Opinion / Certificate

Purpose of the Certificate

The purpose of the RPS Certificate ('Passed' Assessment) is to assist the conveyancer in assessing the implications of the contamination risks identified in the Homecheck Professional Environmental Report. Such risks are identified from a number of key contamination datasets which could lead to the property being defined as "contaminated land" under section 78(A)2 of Part 2A of the Environmental Protection Act 1990.

Under this legislation Local Authorities have a duty to identify land within their Borough which may fall under the definition of "contaminated land". Where land is identified as being "contaminated land", the Local Authority (or the Environment Agency in relation to 'Special Sites') must ensure that the site is remediated and that the land is safe for its use. For a site to be identified as "contaminated land" there must be contamination and a pathway to affect a receptor (e.g. property occupiers or the natural environment) AND be causing, or likely to cause, significant harm. If any one of the contaminant, pathway or receptor components is absent, the property cannot be classed as "contaminated land". Each Local Authority has a contaminated land inspection strategy which outlines the process they will be following to meet their requirements under this legislation.

RPS also provides an Opinion on whether the potential risk will have a significant impact on the security of the property for normal lending purposes.

Other matters covered within the report i.e. Radon and Flood Risk are provided for information purposes only, and are not part of the RPS Certificate.

Methodology and Scope

The RPS opinion is based on a risk assessment model designed by RPS specifically for the purpose described above. The model uses data included in this Homecheck Professional Environmental Report to assess the risk from a number of contamination datasets. Using a point location, the risk model identifies key land uses based on distance from the subject site, significance of the contaminative nature and risk rating.

Review Procedure

Where a potential risk has been identified from the risk model, such that the property does not immediately receive a Passed Certificate, it is forwarded to RPS for manual review by a qualified Environmental Consultant. All reports referred to RPS for review will normally be completed within two working days.

The outcome of the review will either be a Passed Certificate or a Further Action report. Where a Further Action is issued, this does not necessarily mean there is contamination present but that further information is required before a Certificate may be issued. When this happens, further information can either be obtained independently and forwarded to RPS for review, or RPS can be instructed to undertake these enquiries on your behalf.

Please note that the Certificate is based solely on key contamination datasets as detailed in the Homecheck Professional Environmental Report, and is not based on any physical inspection of the property. Whilst Landmark Information Group uses the best available public sources of information to identify possible risks and past land uses, Landmark does not warrant that all potentially contaminative land uses or features, whether past or current, will be identified in the Homecheck Professional Environmental Report.

Further Action (Next Steps)

When a Further Action has been issued for a property there are a number of steps that can be taken. These are explained after the Professional Opinion page at the front of the report. Potential sources of information relating to the property are described below:

- Local Authority Environmental Health Department: To obtain information regarding any past industrial land uses, pollution incidents/records of contamination, past site investigations/remediation, relevant details under the Council's Part 2A strategy and any other concerns regarding ground conditions on and adjacent to the property.
- Local Authority The Planning Department: To obtain information on the development of the property (e.g. a summary planning history) and any existing reports/information on any environmental conditions attached to planning permissions (e.g. a site investigation or remediation work, and confirmation that these conditions have been satisfied).
- Petroleum Officer / Trading Standards Department: For information on a property with potential bulk fuel storage obtain information to confirm if there are any records are held including details of storage tank numbers, volumes, dates of integrity testing and details of any past leaks, spills or issues.

If you require RPS to carry out these enquiries on your behalf the inclusive cost (including provision of a report) will typically be £315+VAT. This cost includes the Authority's own search fees and may take around 10-20 working days dependant on the Authority's response time. Please email: homecheck-query@rpsgroup.com or fax: 020 7403 8858. An invoice will be forwarded to you upon completion.

Who is RPS?

RPS is part of the RPS Group Plc with around 5,000 staff in over 85 offices located throughout the UK, Ireland, USA, Australia and other locations worldwide. RPS offers an unparalleled range of environmental services relating to property, industry and land including due-diligence, geo-environmental investigations, planning & development advice, health & safety, water, energy, sustainability and flood risk consultancy. RPS acts as a panel advisor to the majority of UK clearing banks.

Other Information

The RPS Certificate ONLY applies to a single residential property with a valid planning consent, not to commercial/industrial property.

It is not possible to identify all contaminative land uses from records and historical mapping e.g. illegal tipping of chemical substances or residential heating oil tank leaks.

For any enquiries in relation to this report (including queries for RPS), please contact the Homecheck Professional Environmental Helpline on 0844 844 9966 or at helpdesk@homecheck.co.uk



Search Code

IMPORTANT CONSUMER PROTECTION INFORMATION

This search has been produced by Landmark Information Group Ltd, Imperium, Imperial Way, Reading, Berkshire, RG2 0TD. Telephone: 0844 844 9966, Fax No: 0844 844 9980, email: helpdesk@landmark.co.uk which is registered with the Property Codes Compliance Board (PCCB) as a subscriber to the Search Code. The PCCB independently monitors how registered firms maintain compliance with the Code.

The Search Code:

- Provides protection for homebuyers, sellers, conveyancers and mortgage lenders who rely on the information included in property search reports undertaken by subscribers on residential and commercial property within the United Kingdom.
- Sets out minimum standards which firms compiling and selling search reports have to meet.
- Promotes the best practice and quality standards within the industry for the benefit of consumers and property professionals.
- Enables consumers and property professionals to have confidence in firms which subscribe to the code, their products and services.

By giving you this information, the search firm is confirming that they keep to the principles of the Code. This provides important protection for you.

The Code's core principles

Firms which subscribe to the Code will:

- Display the Code logo prominently on their search reports.
- Act with integrity and carry out work with due skill, care and diligence.
- At all times maintain adequate and appropriate insurance to protect consumers.
- Conduct business in an honest, fair and professional manner.
- Handle complaints speedily and fairly.
- Ensure that all search services comply with the law, registration rules and standards.
- Monitor their compliance with the Code.

COMPLAINTS

If you have a query or complaint about your search, you should raise it directly with the firm, and if appropriate ask for your complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award compensation of up to £5,000 to you if it finds that you have suffered actual loss as a result of your search provider failing to keep to the Code.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPOs or to the PCCB.

TPOs Contact Details:

The Property Ombudsman Scheme
Milford House
43-55 Milford Street
Salisbury
Wiltshire SP1 2BP
Tel: 01722 333306
Fax: 01722 332296
Email: admin@tpos.co.uk

You can get more information about the PCCB from www.propertycodes.org.uk

PLEASE ASK YOUR SEARCH PROVIDER IF YOU WOULD LIKE A COPY OF THE SEARCH CODE



Search Code

COMPLAINTS PROCEDURE

If you want to make a complaint, we will:

- Acknowledge it within 5 working days of its receipt.
- Normally deal with it fully and provide a final response, in writing, within 20 working days of receipt.
- Keep you informed by letter, telephone or e-mail, as you prefer, if we need more time.
- Provide a final response, in writing, at the latest within 40 working days of receipt.
- Liaise, at your request, with anyone acting formally on your behalf.

Complaints should be sent to:

Head of Customer Relations
Landmark Information Group Ltd
Landmark UK Property
Imperium
Imperial Way
Reading
RG2 0TYD

Telephone: 0844 844 9966

E-mail: helpdesk@landmark.co.uk

Fax: 0844 844 9980

If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman Scheme (TPOs): Tel: 01722 333306, E-mail: admin@tpos.co.uk.

We will co-operate fully with the Ombudsman during an investigation and comply with his final decision.