

		EXPLORATORY HOLE PHOTOGRAPHS		Remarks Machine excavated trial pit from GL to 1.50m. No groundwater encountered. 3 soakaway testing cycles in accordance with BRE365 was completed. Backfilled with arisings.		Exploratory Hole TP105
Project	Afan Valley Adventure Resort	Easting	285411.12	Equipment	13 tonne tracked excavator	Sheet 1 of 2
Client	Wildfox Resorts - Afan Valley	Northing	195426.99	Method	TP	
Project No	G22033	Level	303.46 mAOD	Termination Reason	Terminated at scheduled depth	



TP105 Face A




TP105 Face B

		EXPLORATORY HOLE PHOTOGRAPHS		Remarks Machine excavated trial pit from GL to 1.50m. No groundwater encountered. 3 soakaway testing cycles in accordance with BRE365 was completed. Backfilled with arisings.		Exploratory Hole
						TP105
Project	Afan Valley Adventure Resort	Easting	285411.12	Equipment	13 tonne tracked excavator	Sheet 2 of 2
Client	Wildfox Resorts - Afan Valley	Northing	195426.99	Method	TP	
Project No	G22033	Level	303.46 mAOD	Termination Reason	Terminated at scheduled depth	



TP105 Spoil

				TRIAL PIT EXPLORATORY HOLE LOG				Exploratory Hole Progress by Time			Exploratory Hole	
Date and Time		Depth	Water Depth					TP106				
06/07/2022 12:00 06/07/2022 12:20		0.00 1.50	Dry									
Project	Afan Valley Adventure Resort			Equipment	13 tonne tracked excavator			Sheet 1 of 1				
Client	Wildfox Resorts - Afan Valley			Method	TP							
Project No	G22033	Level	259.37 mAOD	Orientation		180 degrees		Scale 1:20				
Easting	285635.70	Northing	195663.02	Length		2.60		Logged SC				
Termination Reason	Terminated at scheduled depth			Width		0.80		Checked AP				
Samples	Sampling and Testing Depths	Insitu Testing and Depth Related Remarks		Depth (Thickness)	Level (mAOD)	Legend	Description			Scale	Backfill	
1 D	0.30 - 0.40			0.00 (0.20)	259.17		Soft dark brown organic SILT with abundant rootlets and roots (30 to 50mm diameter). (TOPSOIL)			0.50		
				0.20 (0.30)		Firm orangish brown very sandy gravelly CLAY. Sand is fine to medium. Gravel is subangular fine to coarse of sandstone. (Weathered RHONDDA MEMBER)						
				0.50	258.87		Firm greyish brown sandy gravelly CLAY with low cobble and boulder content. Sand is medium to coarse. Gravel is angular to subangular fine to coarse of sandstone. Cobbles are subangular of sandstone. Boulders are angular to subangular (300 to 400mm) of sandstone. (Weathered RHONDDA MEMBER)					
2 B	1.00 - 1.30			(1.00)						1.00		
				1.50	257.87		End of Exploratory Hole at 1.50m			1.50		
											2.00	
											2.50	
											3.00	
											3.50	
											4.00	
Weather	Overcast with sunny spells	Trial Pit Excavation Onsite Layout 					Water Strikes					
Shoring	None						Date and Time	Strike	Rising to	Time	Remarks	
Stability	Stable											
Remarks												
Machine excavated trial pit from GL to 1.50m. No groundwater encountered. 1 soakaway testing cycle in accordance with BRE365 was completed. Backfilled with arisings.												