

EXPLORATORY HOLE PHOTOGRAPHS

Remarks
Machine excavated trial pit from GL to 1.60m. No groundwater encountered. 4 soakaway testing cycles in accordance with BRE365 was completed. Backfilled with arisings.

Exploratory Hole
TP111

Project	Afan Valley Adventure Resort	Easting	286382.26	Equipment	13 tonne tracked excavator
Client	Wildfox Resorts - Afan Valley	Northing	195464.88	Method	TP
Project No	G22033	Level	296.88 mAOD	Termination Reason	Terminated at scheduled depth

Sheet 1 of 2



TP111 Face A




TP111 Face B

		EXPLORATORY HOLE PHOTOGRAPHS		Remarks Machine excavated trial pit from GL to 1.60m. No groundwater encountered. 4 soakaway testing cycles in accordance with BRE365 was completed. Backfilled with arisings.		Exploratory Hole
						TP111
Project	Afan Valley Adventure Resort	Easting	286382.26	Equipment	13 tonne tracked excavator	Sheet 2 of 2
Client	Wildfox Resorts - Afan Valley	Northing	195464.88	Method	TP	
Project No	G22033	Level	296.88 mAOD	Termination Reason	Terminated at scheduled depth	



TP111 Spoil

		TRIAL PIT EXPLORATORY HOLE LOG						Exploratory Hole Progress by Time			Exploratory Hole		
								Date and Time		Depth	Water Depth	TP112	
								28/06/2022 10:00 28/06/2022 10:30		0.00 1.50	Dry		
Project	Afan Valley Adventure Resort			Equipment	13 tonne tracked excavator					Sheet 1 of 1			
Client	Wildfox Resorts - Afan Valley			Method	TP					Scale	1:20		
Project No	G22033	Level	274.44 mAOD	Orientation		30 degrees				Logged	SC		
Easting	286425.65	Northing	195608.89	Length		2.90				Checked	AP		
Termination Reason		Terminated at scheduled depth			Width		0.60						
Samples	Sampling and Testing Depths	Insitu Testing and Depth Related Remarks		Depth (Thickness)	Level (mAOD)	Legend	Description			Scale	Backfill		
2 D	0.30 - 0.50			0.00	274.14		Dark brown becoming dark reddish brown soft slightly sandy organic SILT with abundant rootlets. (TOPSOIL)			0.50			
				(0.30)			Orangish brown slightly sandy silty CLAY. Sand is fine. (Weathered RHONDDA MEMBER)						
1 B	1.10 - 1.40			0.30	273.84		Greyish brown gravelly very clayey SAND with low cobble content. Sand is fine to coarse. Gravel is subangular to subrounded fine to coarse of sandstone. Cobbles are subrounded of sandstone. (Weathered RHONDDA MEMBER)			1.00			
				(0.30)									
				0.60						1.50			
				(0.90)	272.94		End of Exploratory Hole at 1.50m			2.00			
										2.50			
										3.00			
										3.50			
										4.00			
Weather	Overcast						Water Strikes						
Shoring	None						Date and Time		Strike	Rising to	Time	Remarks	
Stability	Stable												
Remarks Machine excavated trial pit from GL to 1.50m. No groundwater encountered. 3 soakaway testing cycles in accordance with BRE365 was completed. Backfilled with arisings.													