

Project Name: Gnoll Park, Neath

2080-01-JUB-S-RP-00001-S2-P1

Jubb Project Number: 23157

Appendix B - 2080-01-JUB-S-DR-SK002

Project Name: Gnoll Park, Neath

2080-01-JUB-S-RP-00001-S2-P1

Jubb Project Number: 23157

Appendix C - 2080-01-JUB-S-DR-SK003



C4.2



C4.3



C4.4




C4.5



C4.6



C4.7




GENERAL NOTES:

1. DRAWING NOT TO SCALE.
2. THE SURVEY UNDERTAKEN COVERS INSIDE THE RUINS ONLY AND WAS VISUAL IN NATURE, NO INTRUSIVE WORKS WERE UNDERTAKEN TO ASSESS THE STRUCTURE.
3. PHOTOGRAPHS TAKEN ARE NOT EXHAUSTIVE.

NOTES:

- C4.1 - SIDE OF ROOF ARCH DOES NOT HAVE A BEARING AND MAY NOT BE ADEQUATELY SUPPORTED.
- C4.2 - CORRIDOR 04 HAS A FLAT ROOF.
- C4.3 - DAMAGED GATE.
- C4.4 - FLAT ROOF.
- C4.6 - WOODEN TRUSS ROOF ABOVE STAIRS.
- C4.7 - STAIRS CLOSED OFF BY PRE-CAST CONCRETE.





P1	01.09.23	PR
Rev	Date	Des
PROJECT: THE GNOLL NEATH		
TITLE: RUINS SITE VISIT		
CLIENT: ANDREW SCOTT		
SCALE@A3: NTS		
PROJECT REF: 23157		
DRAWING No: 2080-01-JUB-S-DF		
Revision Reference P = Preliminary A		

Project Name: Gnoll Park, Neath

2080-01-JUB-S-RP-00001-S2-P1

Jubb Project Number: 23157

Appendix D - 2080-01-JUB-S-DR-SK004



GENERAL NOTES:

1. DRAWING NOT TO SCALE.
2. THE SURVEY UNDERTAKEN COVERS INSIDE THE RUINS ONLY AND WAS VISUAL IN NATURE, NO INTRUSIVE WORKS WERE UNDERTAKEN TO ASSESS THE STRUCTURE.
3. PHOTOGRAPHS TAKEN ARE NOT EXHAUSTIVE.

NOTES:

- R6.1 - TIMBER JOISTS IDENTIFIED AT CEILING LEVEL. JOISTS APPEAR TO BE ROTTEN.
- R6.2 - EXPOSED PIPE THROUGH WALL.
- R6.3 - TUNNEL THROUGH WALL. BELIEVED TO BE FOR A CHIMNEY.
- R7.1 - SINGLE PRE-CAST CONCRETE LINTEL SUPPORTING OPENING.
- R7.2 - OPENING ABOVE ARCH.
- C5.1 - LINTELS SUPPORTING PART OF THE ROOF. OPENING ABOVE SECOND ARCH IN CORRIDOR 05.

Rev	Date	Description
P1	01.09.23	PR

PROJECT:
THE GNOLL
NEATH

TITLE:
RUINS SITE VISIT

CLIENT:
ANDREW SCOTT

SCALE@A3:
NTS

PROJECT REF:
23157

DRAWING No:
2080-01-JUB-S-DR

Revision Reference
P = Preliminary A