


Existing trees

Fig.1




- Existing dwelling is sited North of the site.
- T1 – South-West of the property is sited within 20m of the dwelling.
- T2 – South and is sited less than 1m within the dwelling boundary.

Both trees have been classified as C1 with risk failure – (refer to Arboriculture Report)

Proposed Area for replanting

Fig.2



3 trees to be planted to the west of the dwelling highlighted in fig.2