




Photo Ref 84: Detail of the grille at the bottom of the access door to the hall where the heating pipes go down to the basement where the machinery is installed. View from the hallway towards the Hall.



Photo Ref 85: Close-up view of the grille detail.



Photo Ref 86: Detail of the inclined part of the hall ceiling, this area is underneath organ.



Photo Ref 87: Detail of the hall screen, ceiling and columns.



Photo Ref 88: Close-up view of the upper part of the hall column.



Photo Ref 89: Wood and glass full height, articulated panel that separates the hall area from the kitchen and side entrance. View from hall towards the kitchen.



Photo Ref 90: Existing floor finish to the Hall.



Photo Ref 91: Wood and glass full height, articulated panel that separates the Hall area from the kitchen and side entrance, the kitchen panel and the door to access the kitchen. View from side entrance towards the Kitchen.



Photo Ref 92: Front view of the Kitchen panels and door.



Photo Ref 93: Close-up view of the door to access the Kitchen of the chapel.



Photo Ref 94: Internal view of the Kitchen ceiling, wall panels and door.



Photo Ref 95: Detail of the joint of the floating ceiling in the kitchen where an aperture has been created.



Photo Ref 96: Wood and glass full height, articulated panel that separates the hall area from the kitchen and side entrance. View from Kitchen towards the hall.




Photo Ref 97: Hall wall finish and access door. View from hall towards the Chapel.



Photo Ref 98: Internal view of the west elevation exterior door.



Photo Ref 99: Close-up view of the door locks detail.



Photo Ref 100: Front view of the access staircase to the first floor from the West elevation.



Photo Ref 101: Close-up view of the decorative steel balustrade, timber handrail.




Photo Ref 102: Close-up view of the stair gooseneck detail.




Photo Ref 103: Close-up view of the balustrade detail at the top of the staircase.



Photo Ref 104: Existing floor to the first floor in the back area of the chapel. View from staircase access.



Photo Ref 105: Detail of the second floor window sill, this detail is the same for all the windows in room 1 to room 7.



Photo Ref 106: Close-up of the skirting board on room 1, this detail is the same for all the skirting boards in room 1 to room 7.



Photo Ref 107: Close-up view of the skirting board and architrave to room 1, this detail is the same for all the skirting boards and door frames in room 1 to room 7.



Photo Ref 108: Close-up view of the upper part of door frame/architrave from room 1, this detail is the same for all the door frames in room 1 to room 7.



Photo Ref 109: Heating pipe passing through partition wall (rooms 1 and 2).



Photo Ref 110: Heating pipe detail.



Photo Ref 111: Room 3 bellows machinery for the organ.



Photo Ref 112: Close-up view of the bellows lever.



Photo Ref 113: Close-up view of the upper part of the bellows.



Photo Ref 114: Close-up view of the lever and the bellows.



Photo Ref 115: Side view of the duct connecting bellows to the organ (room 3).



Photo Ref 116: View of ducting in room 3.



Photo Ref 117: View of ducting in room 3.



Photo Ref 118: Overall view of the upper part of the bellows.



Photo Ref 119: Decorative timber to the left side of the window in room 3.



Photo Ref 120: Front view of the duct that provides air to the organ passing through room 4 from room 3 to room 5.



Photo Ref 121: Front view of the duct that provides air to the organ passing through room 5.



Photo Ref 122: Side view of the duct that provides air to the organ passing through room 5.



Photo Ref 123: Close-up side view of the duct that provides air to the organ passing through room 5 to room 4.



Photo Ref 124: Overall view of room 6.



Photo Ref 125: General view of the first-floor hallway with the access door to the organ machinery open.



Photo Ref 126: Access door to the closet where organ machinery is installed.



Photo Ref 127: View of the access door to the closet showing the organ machinery.



Photo Ref 128: View of part of the organ machinery.



Photo Ref 129: View of part of the organ machinery.



Photo Ref 130: View of part of the organ machinery.



Photo Ref 131: Stairs that connect the gallery of the chapel with the rear part of the Sunday School.



Photo Ref 132: View of the organ located in the North of the chapel.




Photo Ref 133: Side view of the organ with carved panels. The stool for the organist with adjacent radiator.



Photo Ref 134: Close-up view of the carved panels.



Photo Ref 135: Lateral view of the bench, mirror, music rack, draw knobs and manuals of the organ.




Photo Ref 136: Close-up view of the pedal board, toe studs and swell pedal of the Organ.



Photo Ref 137: Close-up view of the drawknobs on the right side of the organ, including a small door that holds the organ's on/off switch.




Photo Ref 138: Lateral close-up view of the bench and the privacy curtain of the Organ.



Photo Ref 139: Close-up view from below of the flue pipes of the Organ.



Photo Ref 140: Exterior view of the decorative detail of the metal railing with wooden handrails surrounding the Gallery.



Photo Ref 141: Lateral view of the decorative metal railing with wooden handrail defining the gallery.



Photo Ref 142: Top view of the metal railing that surrounds the gallery.




Photo Ref 143: Lower view of the decorative detail of the metal railing surrounding the gallery.



Photo Ref 144: View of hymn board.



Photo Ref 145: Hymn board on either side of the Pulpit Platform.



Photo Ref 146: View of the corner benches on the gallery located either side of the organ.



Photo Ref 147: View of the first-floor windows in the Gallery.



Photo Ref 148: Close-up window opener.



Photo Ref 149: Detail of first floor timber lower part of the window arch.



Photo Ref 150: Detail of decorative window arch. This is on all windows on the first floor.




Photo Ref 151: Lateral view of the middle pews of the gallery.



Photo Ref 152: Lower view of the back pews with heating pipe.




Photo Ref 153: Lower view of the front pews of the gallery showing the heating pipe to the balustrade.



Photo Ref 154: View from the Gallery to the front stairs leading to the main Entrance.




Photo Ref 155: As previous with heating pipe and hand rail.




Photo Ref 156: Lateral view of the first floor gallery pews.



Photo Ref 157: Interior upper views of the window on the main façade with vent flap, all of the upper part of the front windows are the same.



Photo Ref 158: Close-up view of the vent flap (open) showing the full length of the window.




Photo Ref 159: Lateral view of the rear pew facing the corner of the gallery detailing access stairs, the heating pipe and the windows.



Photo Ref 160: As above.



Photo Ref 161: Overall view of the chapel ceiling, showing the lamps and the ventilation grille.



Photo Ref 162: Close-up view of the ceiling corner detail.



Photo Ref 163: Lateral view of the vaulted ceiling.



Photo Ref 164: Close-up view of the coving detail.




Photo Ref 165: Close-up view of the decorative ventilation grille.



Photo Ref 166: View of one of the lamps and ventilation grille.



Photo Ref 167: Close-up view of one of the ceiling lamps, all the lamps in the ceiling are the same.



Photo Ref 168: View of the fence and gates from the main street.




Photo Ref 169: Close view of the fence from the chapel main entrance towards the main street.



Photo Ref 170: View of the gates from the chapel main entrance towards the A4230.




Photo Ref 171: View of the right gates post from the chapel main entrance towards the A4230.




Photo Ref 172: Close view of the right gates post top detail from the chapel main entrance towards the A4230.

Site Location Plan.






SITE PLAN
SCALE 1:500 @ A3



LOCATION PLAN
SCALE 1:1250 @ A3



JOB No: 23.77 Drawing No: A13 scales: 1:1250, 1:500 @ A3	No. REVISION		by	date	No. REVISION		by	date

NOTES 1 Do not scale from this drawing 2 All dimensions to be checked on site	
STAGE	IN PROGRESS

CLIENT
RHIAN JONES & DANIEL KILBRIDE

james&nicholas	
Grove House, Grove Place, Port Talbot SA13 1XA • Tel 01639 885431 • Fax 01639 891687 admin@jamesandnicholas.com • www.jamesandnicholas.com James & Nicholas Limited Liability Partnership. Registered in the UK No. 0C303071	
Job title	PLANNING AND LISTED BUILDING CONSENT, GORFFWYSFA CHAPEL, SKEWEN
Drawing title	LOCATION PLAN AND SITE PLAN

by		date
drawn	MM	24.11.23
checked	JH	24.11.23
approved	JH	24.11.23
Job No:	Drawing No:	Rev:
23.77	A13	/
scales: 1:1250, 1:500 @ A3		

