

3
Small lagoon present in the east of the site (adjacent to TN1), easterly viewpoint.



4
Access road between slab yard and drainage channel, northerly viewpoint.



5
Species rich
area of
EPSV (TN6)
with
adjacent
woodland
(TN5),
southerly
viewpoint.



6
Woodland
north of
Longlands
lane.



7
Example of
floodplain
grassland
(TN4),
northerly
viewpoint.



8
Example of
ditch in
southern
fields
choked with
common
reed (TN4)



9
Structure in southern fields adjacent to Longlands lane.



10
Area of poor semi-improved grassland (TN13) adjacent to large lagoon (TN14) in the north of site, northerly viewpoint.

