

EXPLORATORY HOLE PHOTOGRAPHS

Exploratory Hole

TP03

Project	Dream Fields	Easting	271507.85	Equipment	14t Excavator
Client	Simply Planning	Northing	194729.92	Method	TP
Project No	G25095	Level		Termination Reason	Bedrock encountered, unable to progress

Sheet 1 of 3



Face C



Face A

	EXPLORATORY HOLE PHOTOGRAPHS			Exploratory Hole	
				TP03	
Project	Dream Fields	Easting	271507.85	Equipment	14t Excavator
Client	Simply Planning	Northing	194729.92	Method	TP
Project No	G25095	Level		Termination Reason	Bedrock encountered, unable to progress



Face D



Face B

		EXPLORATORY HOLE PHOTOGRAPHS				Exploratory Hole
						TP03
Project	Dream Fields	Easting	271507.85	Equipment	14t Excavator	Sheet 3 of 3
Client	Simply Planning	Northing	194729.92	Method	TP	
Project No	G25095	Level		Termination Reason	Bedrock encountered, unable to progress	



Spoil

JACKSON GEO SERVICES				TRIAL PIT EXPLORATORY HOLE LOG					Exploratory Hole Progress by Time			Exploratory Hole			
Date and Time		Depth	Water Depth						TP04						
19/08/2025 11:45 19/08/2025 12:20		0.00 4.50	DRY												
Project	Dream Fields			Equipment	14t Excavator			Sheet 1 of 2							
Client	Simply Planning			Method	TP										
Project No	G25095	Level		Orientation		236 degrees									
Easting	271458.36	Northing	194661.70	Length		4.00		Scale 1:20							
Termination Reason		Scheduled depth		Width		1.00		Logged		IR					
								Checked		AP					
Samples	Sampling and Testing Depths	Insitu Testing and Depth Related Remarks		Depth (Thickness)	Level (mAOD)	Legend	Description			Scale	Backfill				
1 ES	0.30 - 0.70			0.00			Orangish brown slightly sandy slightly gravelly SILT with low cobble and boulder content. Sand is fine to medium. Gravel is subrounded to rounded fine to coarse of sandstone. Cobbles are rounded to subangular of sandstone. Boulders are subrounded to rounded up to 400mmx250mmx200mm in size of sandstone. (DEVANSIAN TILL)			0.50					
2 ES	1.40 - 1.70			(1.70)						1.00					
3 ES	1.80 - 2.00			1.70			Greyish brown slightly sandy gravelly SILT with low cobble content and low boulder content. Gravel is subrounded to rounded fine to coarse of sandstone. Cobbles are subangular to rounded of sandstone. Boulders are subrounded to rounded up to 500mmx300mmx120mm in size of sandstone. (DEVANSIAN TILL)			1.50					
										2.00					
										2.50					
4 ES	3.00 - 3.20			(2.80)						3.00					
										3.50					
5 ES	4.00 - 4.50									4.00					
							Continued on next Sheet								
Weather	Cloudy	Trial Pit Excavation Onsite Layout Engineer Face A Face B Face C Face D Excavator Log presents Face A unless otherwise noted.					Water Strikes								
Shoring	None						Date and Time					Strike	Rising to	Time	Remarks
Stability	Stable														
Remarks															
Machine excavated trial pit from GL to 4.50m depth															