

EXPLORATORY HOLE PHOTOGRAPHS

Exploratory Hole

TP04


Project	Dream Fields	Easting	271458.36	Equipment	14t Excavator	Sheet 3 of 3
Client	Simply Planning	Northing	194661.70	Method	TP	
Project No	G25095	Level		Termination Reason	Scheduled depth	



Face A



Face C

		TRIAL PIT EXPLORATORY HOLE LOG						Exploratory Hole Progress by Time			Exploratory Hole		
								Date and Time		Depth	Water Depth	TP05	
								19/08/2025 13:00 19/08/2025 13:20		0.00 1.50	DRY		
Project	Dream Fields			Equipment	JCB 3cx			Sheet 1 of 1					
Client	Simply Planning			Method	TP								
Project No	G25095	Level		Orientation		248 degrees		Scale 1:20					
Easting	271461.80	Northing	194894.43	Length		4.00		Logged IR					
Termination Reason		Bedrock encountered, unable to progress			Width		1.00		Checked AP				
Samples	Sampling and Testing Depths	Insitu Testing and Depth Related Remarks		Depth (Thickness)	Level (mAOD)	Legend	Description			Scale	Backfill		
1 ES	0.20 - 0.60			0.00			Orangish brown slightly sandy slightly gravelly SILT with low cobble content. Sand is fine to medium. Gravel is subrounded to rounded fine to coarse of sandstone. Cobbles are subrounded to rounded of sandstone. (DEVANSIAN TILL)			0.50			
2 ES	1.00 - 1.20			0.90			Dark brown sandy gravelly SILT with low cobble content and low boulder content. Sand is fine to coarse. Gravel is angular to subrounded fine to coarse of sandstone. Cobbles are angular to subangular of sandstone. Boulders are angular to subangular up to 600mmx550mmx80mm of sandstone. (DEVANSIAN TILL)			1.00			
				1.20					Strong dark grey very thinly to thinly bedded coarse grained SANDSTONE. (RHONDDA MEMBER SANDSTONE)			1.50	
							End of Exploratory Hole at 1.50m			2.00			
										2.50			
										3.00			
										3.50			
										4.00			
Weather	Cloudy	Trial Pit Excavation Onsite Layout 					Water Strikes						
Shoring	None						Date and Time		Strike	Rising to	Time	Remarks	
Stability	Stable												
Remarks													
Machine excavated trial pit from GL to 1.50m depth													

Printed 12/09/2025 12:53

	EXPLORATORY HOLE PHOTOGRAPHS			Exploratory Hole	
				TP05	
Project	Dream Fields	Easting	271461.80	Equipment	JCB 3cx
Client	Simply Planning	Northing	194894.43	Method	TP
Project No	G25095	Level		Termination Reason	Bedrock encountered, unable to progress



Face D



Face C